

# **SPECIFICATIONS PROPOSAL & BID DOCUMENT**

IALHB0664-18 – 087  
Property: 1612 West 3<sup>rd</sup> Street

**Sioux City, Iowa**

**Lead Based Paint Remediation must be completed in 10 days from receiving the Notice to Proceed**

**All projects with costs of \$20,000 or more are subject to HUD's pre-approval prior to issuance of a Notice to Proceed.**

**BIDS ARE DUE at the following location on 06/02/2021 no later than 4:00 p.m.  
City of Sioux City: Neighborhood Services Division  
Attn: Matt Meylor  
405 6<sup>th</sup> Street, Room 305  
P.O. Box 447  
Sioux City, IA 51102**

NON-COLLUSION AFFIDAVIT OF PRIME BIDDER

STATE OF) ) SS:  
COUNTY OF)

\_\_\_\_\_, being first duly sworn, deposes and says that:

- (1) He is \_\_\_\_\_ of  
(Owner, partner, office, representative, agent, other, explain)  
\_\_\_\_\_, the Bidder that has submitted the attached Bid;
- (2) He is fully informed respecting the preparation and contents of the attached Bid and of all pertinent circumstances respecting such bid;
- (3) Such Bid is genuine and is not a collusive or sham Bid;
- (4) Neither the said Bidder nor any of its officers, partners, owner, agents, representatives, employees or parties in including this affiant, nor any employee or official of the City of Sioux City has in any way colluded, conspired, connived or agreed, directly or indirectly, with any other Bidder, firm or person to submit a sham bid in connection with the Contract for which the attached Bids have been submitted or to refrain from bidding in connection with such Contract, or has in any manner, directly or indirectly, sought by agreement or collusion or communication or conference with any other Bidder, firm or person to fix the price or prices in the attached Bid or of any other Bidder, or to fix overhead, profit or cost element of the Bid price or the Bid price of any other Bidder, or to secure through any collusion, conspiracy, connivance or unlawful agreement, any advantage against the City of Sioux City or the owner of the property interested in the proposed contract;
- (5) The prices quoted in the attached Bid are fair and proper and are not tainted by any collusion, conspiracy, connivance or unlawful agreement on the part of Bidder or any of its agents, representatives, owners, employers or parties in interest including this affiant, or by any employee or official of the City of Sioux City.

SIGNED

\_\_\_\_\_

TITLE

\_\_\_\_\_

**SIOUX CITY  
LEAD HAZARD CONTROL PROGRAM  
BID AND PROPOSAL**

**PROJECT SPECIFICATIONS FOR PROPERTY LOCATED AT:**

**1612 West 3<sup>rd</sup> Street  
Sioux City, Iowa 51103**

The proposal of \_\_\_\_\_ (hereinafter called "Bidder"), organized and existing under the laws of the State of \_\_\_\_\_ doing business as \* \_\_\_\_\_. (\*Insert "a corporation", "a partnership", or "an individual" as applicable.)

To the City of Sioux City, Iowa (hereinafter called "COMMUNITY").

In compliance with your Advertisement for Bids, BIDDER hereby proposes to perform all WORK for the project located at the above referenced property certifies, and, in the case of a joint BID, each party thereto certifies as to his own organization, that this BID has been arrived at independently, without consultation, communication, or agreement as to any matter related to this BID with any other BIDDER or with any competitor.

BIDDER hereby agrees to commence work under this proposal on or before a date to be specified in the Notice to Proceed.

**BIDDER acknowledges receipt and complete understanding of the Instructions to Bidder:**

---

Printed or typed name of BIDDER / CONTRACTOR

---

Signature of BIDDER / CONTRACTOR

## LINE ITEM PRICING

(CONTRACTOR TO VERIFY QUANTITIES DURING WALKTHROUGH)

<b>NOTE(S):</b> 1) All finish work to be completed per the Bidding Instructions. 2) You are responsible for repairing any damage to components remaining in place (i.e. header and casings as part of window replacement). 3) Per Iowa Admin Code 641-70.2(135) “Paint Stabilization” means repairing any physical defect in the substrate...”			
LINE	ITEM		LEAD
#	INTERIOR DIVISION	LIRA	PRICE
1	Basement, Room 1, Windows, Sash/Frame/Exterior Sash/Exterior Frame (#s 14-18) – Abatement - Remove and replace Window Components. Remove any unnecessary storm windows and ensure all painted surfaces exposed by the activity are covered in a suitable weather resistant material that matches the surrounding. Caulk seams to create dust tight seal.	8 9 267 268 275 276	
2	Basement, Room 1, Support Post (Side Gray) – Interim – Paint stabilization followed by the installation of two coats of high-quality appropriate paint to match existing.	11 12	
3	Basement, Basement Stairway, Stair Header (Side D White) – Interim – Paint stabilization followed by the installation of two coats of high-quality appropriate paint to match existing.	21	
4	Basement, Basement Stairway, Stair Stringer (Side All Gray) – Interim – Paint stabilization followed by the installation of a wear resistant material.	25	
5	Floor 2, 2 <sup>nd</sup> Floor Stairway, Wall/Ceiling (Wall Side A/C/D White)/(Ceiling Side D/All White) – Interim – Paint stabilization followed by the installation of two coats of high-quality appropriate paint to match existing.	27 28 29 30 47	
6	Floor 1, Kitchen, Wall/Ceiling (Wall Side C/D White)/(Ceiling Side All White) – Interim – Paint stabilization followed by the installation of two coats of high-quality appropriate paint to match existing.	122 124 127	
7	Floor 1, Kitchen, Windows, Upper Sash/Lower Sash/Inside Stop/Sill (#s 6/7) – Abatement - Remove and replace Window Components. Remove any unnecessary storm windows and ensure all painted surfaces exposed by the activity are covered in a suitable weather resistant material that matches the surrounding. Caulk seams to create dust tight seal. Sill – Abatement – Strip paint from components and photograph for documentation. Apply two coats of high quality appropriate paint to match surrounding.	129 130 131 132 265	
8	Floor 1, Kitchen, Windows, Casing/Header (# 6/7) – Casing/Header Interim – Paint stabilization followed by the installation of two coats of high-quality appropriate paint to match existing.	128	
9	Floor 1, Dining Room, Windows, Middle Stop/Jamb/Slide/Trough/Exterior Stop (#s 4/5) – Abatement -	108 109 110	

	Remove and replace Window Components. Remove any unnecessary storm windows and ensure all painted surfaces exposed by the activity are covered in a suitable weather resistant material that matches the surrounding. Caulk seams to create dust tight seal.	111 265	
10	Floor 1, Living Room, Windows, Middle Stop/Jamb/Slide/Trough/Exterior Stop (#s 2/3) – Abatement - Remove and replace Window Components. Remove any unnecessary storm windows and ensure all painted surfaces exposed by the activity are covered in a suitable weather resistant material that matches the surrounding. Caulk seams to create dust tight seal.	80 81 83 94 265	
11	Floor 1, Bedroom 2, Windows, Middle Stop/Jamb/Slide/Trough/Exterior Stop (#s 8) – Abatement - Remove and replace Window Components. Remove any unnecessary storm windows and ensure all painted surfaces exposed by the activity are covered in a suitable weather resistant material that matches the surrounding. Caulk seams to create dust tight seal.	211 212 213 214	
12	Floor 1, Bedroom 1, Windows, Middle Stop/Jamb/Slide/Trough/Exterior Stop (#s 1/9) – Abatement - Remove and replace Window Components. Remove any unnecessary storm windows and ensure all painted surfaces exposed by the activity are covered in a suitable weather resistant material that matches the surrounding. Caulk seams to create dust tight seal.	160 161 162 163	
<b>EXTERIOR DIVISION</b>			<b>PRICE</b>
<b>NOTE:</b> If due to colder weather, some or all exterior work may be postponed until warmer conditions. Please make sure that your prices incorporate this, as NO change orders will be issued for additional travel expenses.			
***	If any painted areas are exposed during the completion of activities the price to treat those areas to the same level as the line item should be included.		X
13	Exterior House, Soil, (Side A/B/D) - Install 6-inches of mulch to cover Bare Soil along Side within the drip-line of the house.		
14	Exterior, Upper Wall/Upper Trim/Corner Trim/Lower Trim/Gable Ends (Side All) – Interim – Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing.	238 239 240 241 242 245 246 247	
15	Exterior, Eave/Soffit/Fascia/Soffit Supports (Side All) – Interim – Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing.	243 244 247	

16	Exterior, Entry Door, Casing/Header (Side A) – Interim – Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing.	253	
17	Exterior, Windows, Casing/Header/Sill (# 1/2/3/4/5/6/7/8/9) – Interim – Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing.	259 260 270 271 277 278 264 266	
18	Exterior, Windows, Casing/Header/Sash/Sill (# 10-13) – Interim – Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing.	261 262 263 272 273 274	
	<b>CLEAN UP AND CONTAINMENT DIVISION</b>		<b>PRICE</b>
	This section includes containment and clean-up and waste removal. It may or may not include wrapping of large pieces of furniture and/or appliances. Contractor must clean dwelling sufficiently to pass clearance testing. If containment is utilized, contractor is responsible for establishing containment. If dwelling does not pass clearance on the first attempt, the contractor is responsible for costs associated with subsequent attempts. <b>This line item shall not exceed \$1,500.</b>		\$
	<b>POST REMEDIATION TESTING AND CLEARANCE</b>		<b>PRICE</b>
	Pre-negotiated price for the entirety of the 2018 LHCG. This amount is payable to Impact 7G., Inc. If there are any failed visual inspections they will be billed at a rate of \$300.00 per occurrence, if there are additional inspections that require dust or soil sampling they will be billed at a rate of \$600.00 per occurrence. Any amounts incurred over the initial \$900.00 are the responsibility of the contractor.		\$ 900

<b>BID SUMMARY (1612 West 3<sup>rd</sup> Street)</b>	<b>Base Bid Price</b>
<b>INTERIOR DIVISION TOTAL</b>	\$
<b>EXTERIOR DIVISION TOTAL</b>	\$
<b>CLEAN-UP AND WASTE DIVISION TOTAL</b>	\$
<b>TESTING AND CLEARANCE</b>	\$ 900
<b>TOTAL AMOUNT FOR LEAD BASE BID</b>	\$
<b>ALTERNATE BID ITEMS</b>	
	<b>Alternate Pricing</b>


<b>NOTE:</b> Provide the TOTAL cost for the alternate bid items. If an alternate bid item is selected, the provided cost will replace the costs designated in the "Remove Lines."		
HH Alt	Install provided Smoke and Carbon Monoxide Detectors. Price not to exceed \$25.00	\$
HH Alt	Install drainpipe on hot water heater pressure relief valve per code	
HH Alt		
HH Alt		
Alt		
Alt	<p><b>PERMANENT SOFFIT &amp; FASCIA / METAL COIL WORK -</b>  Entire (complete cover) House/Attached Structures  - Bid to use plastic "Containment" on ground or floor where appropriate. All listed areas are lead hazards. Must use Lead RRP practices.</p> <p>Any exterior door or window trim, (including basement window jambs &amp; trim) not covered in separate specifications.</p> <p>All house overhang soffit, overhang supports including gable braces, and fascia.</p> <p>All overhangs to be finished with vinyl or metal soffit. For lead paint chip containment reasons, use non-vented soffit on overhangs and isolate existing soffit house vents by using vented soffit for these vents only. Include all porch lids and beams. Cover the exterior fascia with pre-painted aluminum coil trim. Face nailing should be minimized. Leave no exterior exposed wood on soffit and fascia.</p>	
	<p><b>PERMANENT SIDING-VINYL - Full cover House and all attached structures.</b>  Notes: - Bid to use plastic "Containment" on ground or floor where appropriate. All listed areas are lead hazards. Must use Lead RRP practices.  - Include all exterior coil work not covered in "soffit /fascia spec" items.  - Leave no original bare or painted wood on the exterior. Wrap all with pre-colored metal.  - All metal edges are to be caulked/sealed inside and outside with silicone to enclose any lead hazard.  - Prepare all surfaces for new siding, including any repair work to existing siding to facilitate new vinyl covering</p> <p>Install 1/4" foam core backer before siding. Fir out all walls that show severe waviness. Furnish and install vinyl siding in standard colors as manufactured by Certainteed (Mainstreet) or equivalent. Siding panels to be no less than .042" thickness.</p>	

	<p>Contractor to install house numbers and reinstall all pre-existing attachments. All work will be done according to manufactures instructions and to Code.</p> <p>This line item would include the re-hanging of the existing gutters unless otherwise specified. This would eliminate all other exterior work.</p>	
--	---	--

**Section to be filled in by City:**

<b>ACCEPTED HEALTHY HOMES ALTERNATES</b>	\$
<b>ACCEPTED LBP ALTERNATES</b>	\$
<b>ADJUSTED BASE BID TOTAL</b>	\$






W 3rd Street

**Legend**  
 ▲ Soil Sample  
 × Dust Sample




JOB DESCRIPTION:	LBP Inspection / Risk Assessment 1612 W 3rd Street Sioux City, Iowa
	SHEET TITLE: Property Map Exterior

DATE:	05/05/21
DRAWN BY:	TS
CHECKED BY:	JR
SCALE:	N/A
PROJECT NO.:	Sioux City LHCG 2018




**Legend**  
 ▲ Soil Sample  
 X Dust Sample



JOB DESCRIPTION: LBP Inspection / Risk Assessment  
 1612 W 3rd Street  
 Sioux City, Iowa


SHEET TITLE: Property Map  
 1st Floor

DATE: 05/05/21  
 DRAWN BY: TS  
 CHECKED BY: JR  
 SCALE: N/A  
 PROJECT NO: Sioux City LHCg 2018



**Legend**

- ▲ Soil Sample
- × Dust Sample



JOB DESCRIPTION: LBP Inspection / Risk Assessment  
 1612 W 3rd Street  
 Sioux City, Iowa

SHEET TITLE: Property Map  
 2nd Floor

DATE: 05/05/21  
 DRAWN BY: TS  
 CHECKED BY: JR  
 SCALE: N/A  
 PROJECT NO: Sioux City LHCG 2018

C

Room 2



Unable to Open 15

16 Unable to Open

B

Room 1

17 Unable to Open

D


Unable to Open 14

18 Unable to Open

A

### Legend

-  Soil Sample
-  Dust Sample



JOB DESCRIPTION:	LBP Inspection / Risk Assessment 1612 W 3rd Street Sioux City, Iowa
SHEET TITLE:	Property Map Basement

DATE:	05/05/21
DRAWN BY:	TS
CHECKED BY:	JR
SCALE:	N/A
PROJECT NO.:	Sioux City LHCG 2018

1612 W 3rd Street - Positive XRF Results

Reading #	Component	Substrate	Side/#	Condition	Color	Hazard	Floor	Room	Result	Concentration	3 SD	Total Pb	Units	Date	Time
8	Window Sash	Wood	14-18	Deteriorated	Black	Cracking	Basement	Room 1	Positive	1	0.2	1.2	mg/cm2	4/6/2021	12:01:12
9	Window Frame	Wood	14-18	Deteriorated	Black	Cracking	Basement	Room 1	Positive	9.4	0.3	9.7	mg/cm2	4/6/2021	12:02:13
11	Support Post	Wood	-	Deteriorated	Gray	Cracking	Basement	Room 1	Positive	6.8	0.3	7.1	mg/cm2	4/6/2021	12:04:24
12	Support Post	Wood	-	Deteriorated	White	Cracking	Basement	Room 1	Positive	6.3	0.3	6.6	mg/cm2	4/6/2021	12:04:35
21	Stair Header	Wood	D	Deteriorated	White	Cracking	Basement	Basement Stairway	Positive	0.9	0.2	1.1	mg/cm2	4/6/2021	12:11:34
25	Stair Stringer	Wood	All	Deteriorated	Gray	Impact	Basement	Basement Stairway	Positive	2.2	0.3	2.5	mg/cm2	4/6/2021	12:14:23
27	Wall	Plaster	A	Deteriorated	White	Cracking	2	2nd Floor Stairway	Positive	4	0.3	4.3	mg/cm2	4/6/2021	12:18:19
28	Wall	Plaster	C	Deteriorated	White	Cracking	2	2nd Floor Stairway	Positive	2.3	0.3	2.6	mg/cm2	4/6/2021	12:18:28
29	Wall	Plaster	D	Deteriorated	White	Cracking	2	2nd Floor Stairway	Positive	3.1	0.3	3.4	mg/cm2	4/6/2021	12:18:40
30	Ceiling	Plaster	All	Deteriorated	White	Cracking	2	2nd Floor Stairway	Positive	4.2	0.3	4.5	mg/cm2	4/6/2021	12:19:00
47	Ceiling	Plaster	D	Deteriorated	White	Cracking	2	2nd Floor Stairway	Positive	2.7	0.3	3	mg/cm2	4/6/2021	12:29:51
80	Window Middle Stop	Wood	2/3	Deteriorated	White	Friction	1	Living Room	Positive	28.9	0.3	29.2	mg/cm2	4/6/2021	12:52:06
81	Window Jamb/Slide	Wood	2/3	Deteriorated	White	Friction	1	Living Room	Positive	29.8	0.3	30.1	mg/cm2	4/6/2021	12:52:22
83	Window Exterior Stop	Wood	2/3	Deteriorated	White	Friction	1	Living Room	Positive	22.5	0.3	22.8	mg/cm2	4/6/2021	12:52:42
94	Window Trough	Wood	2/3	Deteriorated	White	Impact	1	Living Room	Positive	14.1	0.3	14.4	mg/cm2	4/6/2021	12:59:53
108	Window Middle Stop	Wood	4/5	Deteriorated	White	Friction	1	Dining Room	Positive	12.5	0.3	12.8	mg/cm2	4/6/2021	13:07:11
109	Window Jamb/Slide	Wood	4/5	Deteriorated	White	Friction	1	Dining Room	Positive	21.4	0.3	21.7	mg/cm2	4/6/2021	13:07:29
110	Window Trough	Wood	4/5	Deteriorated	White	Impact	1	Dining Room	Positive	11.3	0.3	11.6	mg/cm2	4/6/2021	13:07:48
111	Window Exterior Stop	Wood	4/5	Deteriorated	White	Friction	1	Dining Room	Positive	21.4	0.3	21.7	mg/cm2	4/6/2021	13:07:59
122	Wall	Plaster	C	Deteriorated	White	Cracking	1	Kitchen	Positive	2.5	0.3	2.8	mg/cm2	4/6/2021	13:15:52
124	Ceiling	Plaster	All	Deteriorated	White	Cracking	1	Kitchen	Positive	6	0.3	6.3	mg/cm2	4/6/2021	13:16:17
127	Wall	Plaster	D	Deteriorated	White	Cracking	1	Kitchen	Positive	5.9	0.3	6.2	mg/cm2	4/6/2021	13:18:10
128	Window Casing/Header	Wood	6/7	Deteriorated	White	Cracking	1	Kitchen	Positive	5.8	0.3	6.1	mg/cm2	4/6/2021	13:20:19
129	Window Upper Sash	Wood	6/7	Deteriorated	White	Friction	1	Kitchen	Positive	4.3	0.3	4.6	mg/cm2	4/6/2021	13:20:29
130	Window Lower Sash	Wood	6/7	Deteriorated	White	Friction	1	Kitchen	Positive	6.1	0.3	6.4	mg/cm2	4/6/2021	13:20:40
131	Window Inside Stop	Wood	6/7	Deteriorated	White	Friction	1	Kitchen	Positive	5.4	0.3	5.7	mg/cm2	4/6/2021	13:21:05
132	Window Sill	Wood	6/7	Deteriorated	White	Chewable	1	Kitchen	Positive	5.8	0.3	6.1	mg/cm2	4/6/2021	13:21:17
160	Window Middle Stop	Wood	1/9	Deteriorated	White	Friction	1	Bedroom 1	Positive	10.9	0.3	11.2	mg/cm2	4/6/2021	13:39:47
161	Window Jamb/Slide	Wood	1/9	Deteriorated	White	Friction	1	Bedroom 1	Positive	25.3	0.3	25.6	mg/cm2	4/6/2021	13:39:58
162	Window Trough	Wood	1/9	Deteriorated	White	Impact	1	Bedroom 1	Positive	22.8	0.3	23.1	mg/cm2	4/6/2021	13:40:37
163	Window Exterior Stop	Wood	1/9	Deteriorated	White	Friction	1	Bedroom 1	Positive	20.6	0.3	20.9	mg/cm2	4/6/2021	13:40:45
211	Window Middle Stop	Wood	8	Deteriorated	White	Friction	1	Bedroom 2	Positive	4.9	0.3	5.2	mg/cm2	4/6/2021	14:36:51
212	Window Jamb/Slide	Wood	8	Deteriorated	White	Friction	1	Bedroom 2	Positive	1	0.2	1.2	mg/cm2	4/6/2021	14:36:59
213	Window Trough	Wood	8	Deteriorated	White	Impact	1	Bedroom 2	Positive	21.9	0.3	22.2	mg/cm2	4/6/2021	14:37:20
214	Window Exterior Stop	Wood	8	Deteriorated	White	Friction	1	Bedroom 2	Positive	21.8	0.3	22.1	mg/cm2	4/6/2021	14:37:30
238	Upper Wall	Wood	A	Deteriorated	Gray	Chipping	Exterior	Exterior	Positive	3.1	0.3	3.4	mg/cm2	4/6/2021	15:12:08
239	Upper Wall	Wood	B	Deteriorated	Gray	Chipping	Exterior	Exterior	Positive	11.8	0.3	12.1	mg/cm2	4/6/2021	15:12:24
240	Upper Wall	Wood	C	Deteriorated	Gray	Chipping	Exterior	Exterior	Positive	15.7	0.3	16	mg/cm2	4/6/2021	15:13:10
241	Upper Wall	Wood	D	Deteriorated	Gray	Chipping	Exterior	Exterior	Positive	9.9	0.3	10.2	mg/cm2	4/6/2021	15:14:02
242	Upper Trim	Wood	All	Deteriorated	Gray	Chipping	Exterior	Exterior	Positive	20.5	0.3	20.8	mg/cm2	4/6/2021	15:14:24
243	Eave/Soffit	Wood	All	Deteriorated	Gray	Chipping	Exterior	Exterior	Positive	5.3	0.3	5.6	mg/cm2	4/6/2021	15:14:45
244	Fascia	Wood	All	Deteriorated	White	Chipping	Exterior	Exterior	Positive	12.2	0.3	12.5	mg/cm2	4/6/2021	15:14:53
245	Corner Trim	Wood	All	Deteriorated	White	Chipping	Exterior	Exterior	Positive	21.1	0.3	21.4	mg/cm2	4/6/2021	15:15:12
246	Lower Trim	Wood	All	Deteriorated	White	Chipping	Exterior	Exterior	Positive	22.2	0.3	22.5	mg/cm2	4/6/2021	15:15:23
247	Gable Ends/Soffit Supports	Wood	All	Deteriorated	White	Chipping	Exterior	Exterior	Positive	19.7	0.3	20	mg/cm2	4/6/2021	15:15:59
253	Entry Door Casing/Header	Wood	A	Deteriorated	White	Chipping	Exterior	Exterior	Positive	2.2	0.3	2.5	mg/cm2	4/6/2021	15:19:39
259	Window Casing/Header	Wood	1/2	Deteriorated	White	Chipping	Exterior	Exterior	Positive	1.2	0.2	1.4	mg/cm2	4/6/2021	15:24:23

1612 W 3rd Street - Positive XRF Results

Reading #	Component	Substrate	Side/#	Condition	Color	Hazard	Floor	Room	Result	Concentration	3 SD	Total Pb	Units	Date	Time
260	Window Sill	Wood	1/2	Deteriorated	White	Chipping	Exterior	Exterior	Positive	8.6	0.3	8.9	mg/cm2	4/6/2021	15:24:50
261	Window Casing/Header	Wood	10-12	Deteriorated	White	Chipping	Exterior	Exterior	Positive	8.3	0.3	8.6	mg/cm2	4/6/2021	15:25:48
262	Window Sash	Wood	10-12	Deteriorated	White	Chipping	Exterior	Exterior	Positive	2	0.3	2.3	mg/cm2	4/6/2021	15:25:59
263	Window Sill	Wood	10-12	Deteriorated	White	Chipping	Exterior	Exterior	Positive	10.6	0.3	10.9	mg/cm2	4/6/2021	15:26:08
264	Window Casing/Header	Wood	3-6	Deteriorated	White	Chipping	Exterior	Exterior	Positive	11	0.3	11.3	mg/cm2	4/6/2021	15:27:31
265	Window Sash	Wood	3-6	Deteriorated	Black	Chipping	Exterior	Exterior	Positive	10.4	0.3	10.7	mg/cm2	4/6/2021	15:27:48
266	Window Sill	Wood	3-6	Deteriorated	White	Chipping	Exterior	Exterior	Positive	7.2	0.3	7.5	mg/cm2	4/6/2021	15:28:07
267	Window Frame	Wood	14/15	Deteriorated	White	Chipping	Exterior	Exterior	Positive	18	0.3	18.3	mg/cm2	4/6/2021	15:29:35
268	Window Sash	Wood	14/15	Deteriorated	Black	Chipping	Exterior	Exterior	Positive	2	0.3	2.3	mg/cm2	4/6/2021	15:29:43
270	Window Casing/Header	Wood	7	Deteriorated	White	Chipping	Exterior	Exterior	Positive	12.5	0.3	12.8	mg/cm2	4/6/2021	15:31:27
271	Window Sill	Wood	7	Deteriorated	White	Chipping	Exterior	Exterior	Positive	6	0.3	6.3	mg/cm2	4/6/2021	15:31:36
272	Window Casing/Header	Wood	13	Deteriorated	White	Chipping	Exterior	Exterior	Positive	13	0.3	13.3	mg/cm2	4/6/2021	15:32:56
273	Window Sash	Wood	13	Deteriorated	White	Chipping	Exterior	Exterior	Positive	10.6	0.3	10.9	mg/cm2	4/6/2021	15:33:05
274	Window Sill	Wood	13	Deteriorated	White	Chipping	Exterior	Exterior	Positive	14.5	0.3	14.8	mg/cm2	4/6/2021	15:33:15
275	Window Frame	Wood	16-18	Deteriorated	White	Chipping	Exterior	Exterior	Positive	24.2	0.3	24.5	mg/cm2	4/6/2021	15:34:28
276	Window Sash	Wood	16-18	Deteriorated	Black	Chipping	Exterior	Exterior	Positive	3.4	0.3	3.7	mg/cm2	4/6/2021	15:34:36
277	Window Casing/Header	Wood	8/9	Deteriorated	White	Chipping	Exterior	Exterior	Positive	1.3	0.2	1.5	mg/cm2	4/6/2021	15:35:28
278	Window Sill	Wood	8/9	Deteriorated	White	Chipping	Exterior	Exterior	Positive	16.6	0.3	16.9	mg/cm2	4/6/2021	15:35:42