

# **SPECIFICATIONS PROPOSAL & BID DOCUMENT**

IALHB0664-18 – 097  
Property: 1514 Summit Street

**Sioux City, Iowa**

**Lead Based Paint Remediation must be completed in 10 days from receiving the Notice to Proceed**

**All projects with costs of \$20,000 or more are subject to HUD's pre-approval prior to issuance of a Notice to Proceed.**

**BIDS ARE DUE at the following location on 05/12/2022 no later than 4:00 p.m.  
City of Sioux City: Neighborhood Services Division  
Attn: Matt Meylor  
405 6<sup>th</sup> Street, Room 305  
P.O. Box 447  
Sioux City, IA 51102**

NON-COLLUSION AFFIDAVIT OF PRIME BIDDER

STATE OF) \_\_\_\_\_ ) SS:  
COUNTY OF)

\_\_\_\_\_, being first duly sworn, deposes and says that:

- (1) He is \_\_\_\_\_ of  
(Owner, partner, office, representative, agent, other, explain)  
\_\_\_\_\_, the Bidder that has submitted the attached Bid;
- (2) He is fully informed respecting the preparation and contents of the attached Bid and of all pertinent circumstances respecting such bid;
- (3) Such Bid is genuine and is not a collusive or sham Bid;
- (4) Neither the said Bidder nor any of its officers, partners, owner, agents, representatives, employees or parties in including this affiant, nor any employee or official of the City of Sioux City has in any way colluded, conspired, connived or agreed, directly or indirectly, with any other Bidder, firm or person to submit a sham bid in connection with the Contract for which the attached Bids have been submitted or to refrain from bidding in connection with such Contract, or has in any manner, directly or indirectly, sought by agreement or collusion or communication or conference with any other Bidder, firm or person to fix the price or prices in the attached Bid or of any other Bidder, or to fix overhead, profit or cost element of the Bid price or the Bid price of any other Bidder, or to secure through any collusion, conspiracy, connivance or unlawful agreement, any advantage against the City of Sioux City or the owner of the property interested in the proposed contract;
- (5) The prices quoted in the attached Bid are fair and proper and are not tainted by any collusion, conspiracy, connivance or unlawful agreement on the part of Bidder or any of its agents, representatives, owners, employers or parties in interest including this affiant, or by any employee or official of the City of Sioux City.

SIGNED \_\_\_\_\_

TITLE \_\_\_\_\_

**SIOUX CITY  
LEAD HAZARD CONTROL PROGRAM  
BID AND PROPOSAL**

**PROJECT SPECIFICATIONS FOR PROPERTY LOCATED AT:**

**1514 Summit Street  
Sioux City, Iowa 51103**

The proposal of \_\_\_\_\_ (hereinafter called "Bidder"), organized and existing under the laws of the State of \_\_\_\_\_ doing business as \* \_\_\_\_\_. (\*Insert "a corporation", "a partnership", or "an individual" as applicable.)

To the City of Sioux City, Iowa (hereinafter called "COMMUNITY").

In compliance with your Advertisement for Bids, BIDDER hereby proposes to perform all WORK for the project located at the above referenced property certifies, and, in the case of a joint BID, each party thereto certifies as to his own organization, that this BID has been arrived at independently, without consultation, communication, or agreement as to any matter related to this BID with any other BIDDER or with any competitor.

BIDDER hereby agrees to commence work under this proposal on or before a date to be specified in the Notice to Proceed.

**BIDDER acknowledges receipt and complete understanding of the Instructions to Bidder:**

\_\_\_\_\_  
Printed or typed name of BIDDER / CONTRACTOR

\_\_\_\_\_  
Signature of BIDDER / CONTRACTOR

## LINE ITEM PRICING

(CONTRACTOR TO VERIFY QUANTITIES DURING WALKTHROUGH)

<b>NOTE(S):</b> 1) All finish work to be completed per the Bidding Instructions. 2) You are responsible for repairing any damage to components remaining in place (i.e. header and casings as part of window replacement). 3) Per Iowa Admin Code 641-70.2(135) “Paint Stabilization” means repairing any physical defect in the substrate...”			
LINE	ITEM		LEAD
#	INTERIOR DIVISION	LIRA	PRICE
1	Basement, Room 1, Angle Wall (Side C White)/Support Post (Side D Yellow/White)/Beam (Side B/D White) Interim – Paint stabilization followed by the installation of two coats of high-quality appropriate paint to match existing.	86 89 90 94	
2	Basement, Room 1, Windows, Frame/Sash (#s 26) - Abatement - Remove and replace Window Components. Remove any unnecessary storm windows and ensure all painted surfaces exposed by the activity are covered in a suitable weather resistant material that matches the surrounding. Caulk seams to create dust tight seal.	91 92	
3	Basement, Room 2, Windows, Frame/Sash (#s 27/28) - Abatement - Remove and replace Window Components. Remove any unnecessary storm windows and ensure all painted surfaces exposed by the activity are covered in a suitable weather resistant material that matches the surrounding. Caulk seams to create dust tight seal.	100 101	
4	Basement, Room 2, Wall (Side A Gray)/Angle Wall/Angel Wall Shelf/Support Post/Door Support Post (Side D Gray) Interim – Paint stabilization followed by the installation of two coats of high-quality appropriate paint to match existing.	102 107 109 114 115	
5	Basement, Room 2, To Room 1 Door, Casing/Header (Side A Gray) Interim – Paint stabilization followed by the installation of two coats of high-quality appropriate paint to match existing.	116	
6	Basement, Room 3, Windows, Frame/Sash (#s 30) - Abatement - Remove and replace Window Components. Remove any unnecessary storm windows and ensure all painted surfaces exposed by the activity are covered in a suitable weather resistant material that matches the surrounding. Caulk seams to create dust tight seal.	39 40	
7	Basement, Room 3, To Room 2, Upper Beam (Side B White/Green) Interim – Paint stabilization followed by the installation of two coats of high-quality appropriate paint to match existing.	47 48	
8	Basement, Room 3 Closet, Windows, Frame/Sash (#s 29) - Abatement - Remove and replace Window Components. Remove any unnecessary storm windows and ensure all painted surfaces exposed by the activity are covered in a suitable	59 60	

	weather resistant material that matches the surrounding. Caulk seams to create dust tight seal.		
9	Basement, Basement Entry, Above Door Frame (Side A White) Interim – Paint stabilization followed by the installation of two coats of high-quality appropriate paint to match existing.	66	
10	Basement, Bedroom 6, Entry Door, Jamb (Side C Brown) - Abatement – Strip paint from Jamb and photograph for documentation / paint stabilization on the entire side of failing component followed by the application of two coats of high-quality appropriate paint.	12	
11	Basement, Basement Stairway, Joist (Side A/C/D White)/Lower Wall (Side A White)/Stair Stringer (Side A/C Gray)/Stair Railing Support (Side C Gray)/Wall (Side B White) Interim – Paint stabilization followed by the installation of two coats of high-quality appropriate paint to match existing.	133 134 137 139 140	
12	Floor 1, Kitchen 2, Windows, Middle Stop/Jamb (#s 7) - Abatement – Strip paint from all impact/friction surfaces on Components and photograph for documentation / paint stabilization on the entire side of failing component followed by the application of two coats of high-quality appropriate paint.	178 179	
13	Floor 1, Kitchen 2, Cabinet Inner Frame (Side A Pink) Interim – Paint stabilization followed by the installation of two coats of high-quality appropriate paint to match existing.	184	
14	Floor 1, Rear Entry, To Kitchen 1 Door, Jamb/Stop/Door (Side A White)/Entry Door Exterior (Side B From Kitchen 1) - Abatement – Remove and replace Stop, Strip paint from Jamb, Strip paint 2 inches from all impact/friction surfaces on Door and photograph for documentation / paint stabilization on the entire side of failing component followed by the application of two coats of high-quality appropriate paint.	164 165 166 208	
15	Floor 1, Rear Entry, To Kitchen 1 Door, Casing/Header (Side A White) Interim – Paint stabilization followed by the installation of two coats of high-quality appropriate paint to match existing.	163	
16	Floor 1, Rear Entry, Entry Door, Jamb/Stop/Door/Threshold/Sill (Side D White/Gray/Pink)Exterior Door (Side D Green) - Abatement – Remove and replace Stop, Strip paint from Jamb/Threshold/Sill, Strip paint 2 inches from all impact/friction surfaces on Door and photograph for documentation / paint stabilization on the entire side of failing component followed by the application of two coats of high-quality appropriate paint.	156 157 158 160 161 162 664	
17	Floor 1, Rear Entry, Entry Door, Casing/Header (Side D White) Interim – Paint stabilization followed by the installation of two coats of high-quality appropriate paint to match existing.	155	
18	Floor 1, Rear Entry, Windows, Sash/Sill (#s 6) Interim – Paint stabilization followed by the installation of two coats of high-quality appropriate paint to match existing.	151 154	

19	Floor 1, Rear Entry, Wall/Baseboard (Side All) Interim – Paint stabilization followed by the installation of two coats of high-quality appropriate paint to match existing.	141 142 143 144 147	
20	Floor 1, Dining Room, Entry Door, Stop/Sill (Side D White/Blue) - Abatement – Remove and replace Stop, Strip paint from Sill and photograph for documentation / paint stabilization on the entire side of failing component followed by the application of two coats of high-quality appropriate paint.	258 261	
21	Floor 1, Front Entry, Ceiling (Side All) Interim – Paint stabilization followed by the installation of two coats of high-quality appropriate paint to match existing.	305	
22	Floor 1, Front Entry, Entry Door, Stop/Sill (Side A White/Blue) - Abatement – Remove and replace Stop, Strip paint from Sill and photograph for documentation / paint stabilization on the entire side of failing component followed by the application of two coats of high-quality appropriate paint.	311 314	
23	Floor 2, Main Stairway, Ceiling (Side All) Interim – Paint stabilization followed by the installation of two coats of high-quality appropriate paint to match existing.	401	
24	Floor 2, Hallway, Ceiling (Side All) Interim – Paint stabilization followed by the installation of two coats of high-quality appropriate paint to match existing.	419	
25	Floor 2, Attic Stairway, Mid Wall (Side B Beige)/Stair Stringer (Side All)/Mid Wall Newel Post (Side -) Interim – Paint stabilization followed by the installation of two coats of high-quality appropriate paint to match existing.	442 445 448	
26	Floor 2, Attic Stairway, Stair Tread/Riser (Side All) – Interim – Paint film stabilization followed by the installation of a wear resistant material.	443 444	
27	Floor 2, Attic Stairway, Mid Wall Railing (Side - Beige) - Abatement – Remove and replace Railing followed by the application of two coats of high-quality appropriate paint.	447	
28	Floor 2, Bedroom 2, Windows, Sill (#s 25) - Abatement – Strip paint from Sill and photograph for documentation / paint stabilization on the entire side of failing component followed by the application of two coats of high-quality appropriate paint.	469	
29	Floor 2, Bedroom 2, Entry Door, Jamb/Door (Side B White) - Abatement – Strip paint from Jamb, Strip paint 2 inches from all impact/friction surfaces on Door and photograph for documentation / paint stabilization on the entire side of failing component followed by the application of two coats of high-quality appropriate paint.	471 474	
30	Floor 2, Bedroom 2, Closet Door, Jamb/Stop (Side B/White) - Abatement – Remove and replace Stop, Strip paint from Jamb, and photograph for documentation / paint stabilization on the entire side of failing component followed by the application of two coats of high-quality appropriate paint.	476 477	

	Floor 2, Bedroom 2 Closet, Windows, Sill (#s 12) - Abatement – Strip paint from Sill and photograph for documentation / paint stabilization on the entire side of failing component followed by the application of two coats of high-quality appropriate paint.	481	
31	Floor 2, Bedroom 2 Closet, Shelf (Side All) – Interim – Paint film stabilization followed by the installation of a wear resistant material.	488	
32	Floor 2, Bedroom 3, Windows, Sill (#s 13/14) - Abatement – Strip paint from Sill and photograph for documentation / paint stabilization on the entire side of failing component followed by the application of two coats of high-quality appropriate paint.	502	
33	Floor 2, Bedroom 3, Entry Door, Jamb/Stop/Door (Side C White) - Abatement – Remove and replace Stop, Strip paint from Jamb, Strip paint 2 inches from all impact/friction surfaces on Door and photograph for documentation / paint stabilization on the entire side of failing component followed by the application of two coats of high-quality appropriate paint.	504 505 507	
34	Floor 2, Bedroom 3, Closet Door, Jamb/Stop/Door (Side D Beige/White)/Door (Side B From Closet) - Abatement – Remove and replace Stop, Strip paint from Jamb, Strip paint 2 inches from all impact/friction surfaces on Door and photograph for documentation / paint stabilization on the entire side of failing component followed by the application of two coats of high-quality appropriate paint.	509 510 511 524	
35	Floor 2, Bedroom 3 Closet, Ceiling/Baseboard (Side All)/Under Stair Riser (Side A Green)/Wall (Side B/C/D) Interim – Paint stabilization followed by the installation of two coats of high-quality appropriate paint to match existing.	512 513 514 515 516 521	
36	Floor 2, Bedroom 3 Closet, Door, Casing/Header (Side B Beige) Interim – Paint stabilization followed by the installation of two coats of high-quality appropriate paint to match existing.	523	
37	Floor 2, Bedroom 4, Entry Door, Jamb/Stop/Door (Side D White) - Abatement – Remove and replace Stop, Strip paint from Jamb, Strip paint 2 inches from all impact/friction surfaces on Door and photograph for documentation / paint stabilization on the entire side of failing component followed by the application of two coats of high-quality appropriate paint.	537 538 540	
38	Floor 2, Bedroom 4, Closet Door, Jamb/Stop (Side A White) - Abatement – Remove and replace Stop, Strip paint from Jamb, and photograph for documentation / paint stabilization on the entire side of failing component followed by the application of two coats of high-quality appropriate paint.	542 543	
39	Floor 2, Bedroom 4, Closet Door, Casing/Header (Side A White) Interim – Paint stabilization followed by the installation of two coats of high-quality appropriate paint to match existing.	541	
40	Floor 2, Bathroom 2, Entry Door, Jamb/Stop (Side A White) - Abatement – Remove and replace Stop, Strip paint from Jamb, and photograph for documentation / paint stabilization on the	565 566	

	entire side of failing component followed by the application of two coats of high-quality appropriate paint.		
41	Floor 2, Bathroom 2, Closet Door, Casing/Header (Side D Beige) Interim – Paint stabilization followed by the installation of two coats of high-quality appropriate paint to match existing.	569	
42	Floor 2, Bathroom 2, Closet Door, Door (Side D White)/(Side B From Closet) - Abatement – Strip paint 2 inches from all impact/friction surfaces on Door and photograph for documentation / paint stabilization on the entire side of failing component followed by the application of two coats of high-quality appropriate paint.	570 578	
43	Floor 2, Bathroom 2 Closet, Shelf Underside (Side All White) Interim – Paint stabilization followed by the installation of two coats of high-quality appropriate paint to match existing.	577	
44	Floor 2, Bedroom 5, Windows, Sill (#s 23) - Abatement – Strip paint from Sill and photograph for documentation / paint stabilization on the entire side of failing component followed by the application of two coats of high-quality appropriate paint.	596	
45	Floor 2, Bedroom 5, Entry Door, Jamb/Stop/Door (Side B White) - Abatement – Remove and replace Stop, Strip paint from Jamb, Strip paint 2 inches from all impact/friction surfaces on Door and photograph for documentation / paint stabilization on the entire side of failing component followed by the application of two coats of high-quality appropriate paint.	598 599 601	
46	Floor 2, Bedroom 5 Closet, Baseboard (Side All White) Interim – Paint stabilization followed by the installation of two coats of high-quality appropriate paint to match existing.	612	
47	Floor 2, Bedroom 5 Closet, Shoe Molding (Side All White) - Abatement – Remove and replace component followed by the application of two coats of high quality paint to match surrounding.	613	
	<b>EXTERIOR DIVISION</b>		<b>PRICE</b>
<b>NOTE:</b> If due to colder weather, some or all exterior work may be postponed until warmer conditions. Please make sure that your prices incorporate this, as NO change orders will be issued for additional travel expenses.			
***	If any painted areas are exposed during the completion of activities the price to treat those areas to the same level as the line item should be included.		X
48	Exterior House/Flower Bed, Soil, (Side B/Flower Bed Side A) - Install 6-inches of mulch to cover Bare Soil along Side within the drip-line of the house.		
49	Exterior Flower Bed, Bare Soil (Side C/D Flower Bed) – Abatement – Remove soil to a depth of 6 inches. Backfill with soil that is proved to contain <400 ppm of lead through lab analysis. Plant grass seed to cover backfilled soil and Bare Soil immediately outside the backfilled area.		



50	Exterior, Eave/Soffit/Fascia/Soffit Supports (Side All) – Interim – Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing.	622 623 624	
51	Exterior, Patio 1, Upper Beam/Crown Molding/Upper Trim/Soffit/Column/Lower Trim (Side All) – Interim – Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing.	642 643 644 645 648 649	
52	Exterior, Patio 2, Upper Beam/Crown Molding/Upper Trim/Soffit (Side All) – Interim – Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing.	677 678 679 680	
53	Exterior, Windows, Casing/Header/Sill (#s 3-8/15-21) – Interim – Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing.	666 667 668 670 672 673	
54	Exterior, Windows, Sill (#s 1/2/10//12/23) – Interim – Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing.	629 636 638	
55	Exterior, Windows, Casing/Header (#s 5/9/22/24/25) – Interim – Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing.	930 933 975	
56	Exterior, Windows, Sash (#s 6) – Interim – Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing.	669	
57	Exterior, Windows, Exterior Stop (#s 6/8) – Interim – Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing.	671	
58	Exterior, Entry Door, Sill (Side A Green) - Abatement – Strip paint from Sill and photograph for documentation / paint stabilization on the entire side of failing component followed by the application of two coats of high-quality appropriate paint.	640	
59	Exterior, Exterior Garage, Upper Wall (Side A/B/D)/Upper Trim/Corner Trim (Side All)/Gable Wall/Mid Wall Trim (Side C) – Interim – Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing.	687 688 689 692 705 706 708	
60	Exterior, Exterior Garage, Eave/Soffit/Fascia (Side All) – Interim – Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing.	690 691	
61	Exterior, Exterior Garage, Entry Door, Casing/Header (Side B White) – Interim – Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing.	693	
62	Exterior, Exterior Garage, Entry Door, Jamb/Stop/Door (Side B White/Brown) - Abatement – Remove and replace Stop, Strip paint from Jamb, Strip paint 2 inches from all impact/friction surfaces on Door and photograph for documentation / paint stabilization on the entire side of failing component followed by the application of two coats of high-quality appropriate paint.	694 695 696	

63	Exterior, Exterior Garage, Overhead Door, Casing/Header (Side C White) – Interim – Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing.	709	
64	Exterior, Exterior Garage, Overhead Door, Jamb/Stop (Side C White) - Abatement – Remove and replace Stop, Strip paint from Jamb, and photograph for documentation / paint stabilization on the entire side of failing component followed by the application of two coats of high-quality appropriate paint.	711 713	
65	Exterior, Exterior Garage, Windows, Casing/Header/Sill (#s 34) – Interim – Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing.	697 700 701	
66	Exterior, Exterior Garage, Windows, Jamb/Stop (#s 34) - Abatement – Remove and replace Stop, Strip paint from Jamb, and photograph for documentation / paint stabilization on the entire side of failing component followed by the application of two coats of high-quality appropriate paint.	698 699	
	<b>CLEAN UP AND CONTAINMENT DIVISION</b>		<b>PRICE</b>
	This section includes containment and clean-up and waste removal. It may or may not include wrapping of large pieces of furniture and/or appliances. Contractor must clean dwelling sufficiently to pass clearance testing. If containment is utilized, contractor is responsible for establishing containment. If dwelling does not pass clearance on the first attempt, the contractor is responsible for costs associated with subsequent attempts. <b>This line item shall not exceed \$1,500.</b>		\$
	<b>POST REMEDIATION TESTING AND CLEARANCE</b>		<b>PRICE</b>
	Pre-negotiated price for the entirety of the 2018 LHCG. This amount is payable to Impact 7G., Inc. If there are any failed visual inspections they will be billed at a rate of \$300.00 per occurrence, if there are additional inspections that require dust or soil sampling they will be billed at a rate of \$600.00 per occurrence. Any amounts incurred over the initial \$900.00 are the responsibility of the contractor.		\$ 900



<b>BID SUMMARY (1514 Summit Street)</b>	<b>Base Bid Price</b>
<b>INTERIOR DIVISION TOTAL</b>	\$
<b>EXTERIOR DIVISION TOTAL</b>	\$
<b>CLEAN-UP AND WASTE DIVISION TOTAL</b>	\$
<b>TESTING AND CLEARANCE</b>	\$ 900
<b>TOTAL AMOUNT FOR LEAD BASE BID</b>	\$
<b>ALTERNATE BID ITEMS</b>	

		<b>Alternate Pricing</b>
<b>NOTE:</b> Provide the TOTAL cost for the alternate bid items. If an alternate bid item is selected, the provided cost will replace the costs designated in the "Remove Lines."		
HH Alt	Install Smoke and Carbon Monoxide Detectors. Install Smoke detectors on each floor and Carbon Monoxide detectors in sleeping areas.	\$
HH Alt	Install wire nut and blank cover plat at open junction box on basement ceiling.	

**Section to be filled in by City:**

<b>ACCEPTED HEALTHY HOMES ALTERNATES</b>	\$
<b>ACCEPTED LBP ALTERNATES</b>	\$
<b>ADJUSTED BASE BID TOTAL</b>	\$

Summit Street



### Legend

-  Soil Sample
-  Dust Sample
- V = Vinyl
- M = Metal




JOB DESCRIPTION: LBP Inspection / Risk Assessment  
1514 Summit Street  
Sioux City, Iowa

SHEET TITLE: Property Map  
Exterior

DATE: 04/13/22  
DRAWN BY: TS  
CHECKED BY: JR  
SCALE: N/A  
PROJECT NO: Sioux City LHCG 2018





**Legend**


- ▲ Soil Sample
- × Dust Sample
- V = Vinyl
- M = Metal




JOB DESCRIPTION: LBP Inspection / Risk Assessment  
1514 Summit Street  
Sioux City, Iowa

SHEET TITLE: Property Map  
1st Floor

DATE: 04/13/22  
 DRAWN BY: TS  
 CHECKED BY: JR  
 SCALE: N/A  
 PROJECT NO: Sioux City LHCG 2018





**Legend**


- ▲ Soil Sample
- × Dust Sample
- V = Vinyl
- M = Metal




JOB DESCRIPTION: LBP Inspection / Risk Assessment  
1514 Summit Street  
Sioux City, Iowa

SHEET TITLE: Property Map  
2nd Floor

DATE: 04/13/22  
 DRAWN BY: TS  
 CHECKED BY: JR  
 SCALE: N/A  
 PROJECT NO: Sioux City LHCG 2018





**Legend**

- ▲ Soil Sample
- × Dust Sample
- V = Vinyl
- M = Metal



JOB DESCRIPTION: LBP Inspection / Risk Assessment  
1514 Summit Street  
Sioux City, Iowa

SHEET TITLE: Property Map  
Attic


DATE: 04/13/22

DRAWN BY: TS

CHECKED BY: JR

SCALE: N/A

PROJECT NO: Sioux City LHCG 2018



**Legend**


- ▲ Soil Sample
- × Dust Sample
- V = Vinyl
- M = Metal



JOB DESCRIPTION: LBP Inspection / Risk Assessment  
1514 Summit Street  
Sioux City, Iowa

SHEET TITLE: Property Map  
Basement

DATE: 04/13/22  
DRAWN BY: TS  
CHECKED BY: JR  
SCALE: N/A  
PROJECT NO: Sioux City LHCG 2018





## 1514 Summit Street - Positive XRF Results

Reading	Component	Substrate	Side/#	Condition	Color	Hazard	Floor	Room	Result	Concentration	3 SD	Total Pb	Units	Date	Time
12	Entry Door Jamb	Wood	C	Deteriorated	Brown	Friction	Basement	Bedroom 6	Positive	10	0.3	10.3	mg/cm2	4/8/2022	12:38:51
39	Window Frame	Wood	30	Deteriorated	Green	Friction	Basement	Room 3	Positive	18.4	0.5	18.9	mg/cm2	4/8/2022	12:55:13
40	Window Sash	Wood	30	Deteriorated	Green	Friction/Impact	Basement	Room 3	Positive	20.3	0.5	20.8	mg/cm2	4/8/2022	12:55:21
47	To Room 2 Door Upper Beam	Wood	B	Deteriorated	White	Cracking	Basement	Room 3	Positive	15.3	0.5	15.8	mg/cm2	4/8/2022	13:00:26
48	To Room 2 Door Upper Beam	Wood	B	Deteriorated	Green	Cracking	Basement	Room 3	Positive	12.2	0.3	12.5	mg/cm2	4/8/2022	13:00:34
59	Window Sash	Wood	29	Deteriorated	Brown	Friction/Impact	Basement	Room 3 Closet	Positive	15.1	0.5	15.6	mg/cm2	4/8/2022	13:06:53
60	Window Frame	Wood	29	Deteriorated	Brown	Friction	Basement	Room 3 Closet	Positive	7	0.3	7.3	mg/cm2	4/8/2022	13:07:07
66	Above Door Frame	Wood	A	Deteriorated	White	Cracking	Basement	Basement Entry	Positive	18.4	0.5	18.9	mg/cm2	4/8/2022	13:14:52
86	Angle Wall	Wood	C	Deteriorated	White	Cracking	Basement	Room 1	Positive	10.5	0.5	11	mg/cm2	4/8/2022	13:24:33
89	Support Post	Wood	D	Deteriorated	Yellow	Cracking	Basement	Room 1	Positive	6.4	0.3	6.7	mg/cm2	4/8/2022	13:25:26
90	Support Post	Wood	D	Deteriorated	White	Cracking	Basement	Room 1	Positive	30	1	31	mg/cm2	4/8/2022	13:25:39
91	Window Frame	Wood	26	Deteriorated	Brown	Friction	Basement	Room 1	Positive	10.8	0.5	11.3	mg/cm2	4/8/2022	13:26:08
92	Window Sash	Wood	26	Deteriorated	Brown	Friction/Impact	Basement	Room 1	Positive	12.8	0.5	13.3	mg/cm2	4/8/2022	13:26:16
94	Beam	Wood	B/D	Deteriorated	White	Cracking	Basement	Room 1	Positive	25.2	0.5	25.7	mg/cm2	4/8/2022	13:27:00
100	Window Frame	Wood	27/28	Deteriorated	White	Friction	Basement	Room 2	Positive	14	0.5	14.5	mg/cm2	4/8/2022	13:31:19
101	Window Sash	Wood	27/28	Deteriorated	White	Friction/Impact	Basement	Room 2	Positive	11.8	0.5	12.3	mg/cm2	4/8/2022	13:31:27
102	Wall	Wood	A	Deteriorated	Gray	Cracking	Basement	Room 2	Positive	9	0.3	9.3	mg/cm2	4/8/2022	13:33:43
107	Angle Wall	Wood	D	Deteriorated	Gray	Cracking	Basement	Room 2	Positive	7.4	0.3	7.7	mg/cm2	4/8/2022	13:34:44
109	Angle Wall Shelf	Wood	D	Deteriorated	Gray	Cracking	Basement	Room 2	Positive	13.2	0.3	13.5	mg/cm2	4/8/2022	13:35:05
114	Support Post	Wood	D	Deteriorated	Gray	Cracking	Basement	Room 2	Positive	13.2	0.3	13.5	mg/cm2	4/8/2022	13:37:52
115	Door Support Post	Wood	D	Deteriorated	Gray	Cracking	Basement	Room 2	Positive	9.2	0.3	9.5	mg/cm2	4/8/2022	13:38:01
116	To Room 1 Door Casing	Wood	A	Deteriorated	Gray	Cracking	Basement	Room 2	Positive	13.5	0.5	14	mg/cm2	4/8/2022	13:38:50
133	Joist	Wood	A/C/D	Deteriorated	White	Cracking	Basement	Basement Stairway	Positive	10.4	0.3	10.7	mg/cm2	4/8/2022	13:51:47
134	Lower Wall	Wood	A	Deteriorated	White	Cracking	Basement	Basement Stairway	Positive	14.1	0.5	14.6	mg/cm2	4/8/2022	13:52:33
137	Stair Stringer	Wood	A/C	Deteriorated	Gray	Cracking	Basement	Basement Stairway	Positive	4.6	0.3	4.9	mg/cm2	4/8/2022	13:54:08
139	Stair Railing Support	Wood	C	Deteriorated	Gray	Cracking	Basement	Basement Stairway	Positive	8.5	0.3	8.8	mg/cm2	4/8/2022	13:54:51
140	Wall	Plaster	B	Deteriorated	White	Cracking	Basement	Basement Stairway	Positive	2.7	0.3	3	mg/cm2	4/8/2022	13:55:58
141	Wall	Plaster	A	Deteriorated	White	Cracking	1	Rear Entry	Positive	20.7	0.3	21	mg/cm2	4/8/2022	14:02:09
142	Wall	Plaster	B	Deteriorated	White	Cracking	1	Rear Entry	Positive	13.6	0.3	13.9	mg/cm2	4/8/2022	14:02:21
143	Wall	Plaster	C	Deteriorated	White	Cracking	1	Rear Entry	Positive	21.6	0.3	21.9	mg/cm2	4/8/2022	14:02:30
144	Wall	Plaster	D	Deteriorated	White	Cracking	1	Rear Entry	Positive	18.6	0.3	18.9	mg/cm2	4/8/2022	14:02:39
147	Baseboard	Wood	All	Deteriorated	White	Cracking	1	Rear Entry	Positive	5.7	0.3	6	mg/cm2	4/8/2022	14:03:22
151	Window Sash	Wood	6	Deteriorated	White	Cracking	1	Rear Entry	Positive	4.1	0.3	4.4	mg/cm2	4/8/2022	14:06:47
154	Window Sill	Wood	6	Deteriorated	White	Cracking	1	Rear Entry	Positive	2.8	0.3	3.1	mg/cm2	4/8/2022	14:07:11
155	Entry Door Casing/Header	Wood	D	Deteriorated	White	Cracking	1	Rear Entry	Positive	6.6	0.3	6.9	mg/cm2	4/8/2022	14:12:00
156	Entry Door Jamb	Wood	D	Deteriorated	White	Friction	1	Rear Entry	Positive	5.7	0.3	6	mg/cm2	4/8/2022	14:12:09
157	Entry Door Stop	Wood	D	Deteriorated	Gray	Impact	1	Rear Entry	Positive	47	1	48	mg/cm2	4/8/2022	14:12:21
158	Entry Door	Wood	D	Deteriorated	White	Friction/Impact	1	Rear Entry	Positive	5	0.3	5.3	mg/cm2	4/8/2022	14:12:47
160	Entry Door Threshold	Wood	D	Deteriorated	Pink	Friction	1	Rear Entry	Positive	13.5	0.3	13.8	mg/cm2	4/8/2022	14:13:24
161	Entry Door Sill	Wood	D	Deteriorated	Pink	Friction	1	Rear Entry	Positive	13.1	0.3	13.4	mg/cm2	4/8/2022	14:13:33
162	Entry Door	Wood	D	Deteriorated	White	Friction/Impact	1	Rear Entry	Positive	7.8	0.3	8.1	mg/cm2	4/8/2022	14:13:56
163	To Kitchen 1 Door Casing/Header	Wood	A	Deteriorated	White	Cracking	1	Rear Entry	Positive	4.8	0.3	5.1	mg/cm2	4/8/2022	14:17:46
164	To Kitchen 1 Door Jamb	Wood	A	Deteriorated	White	Friction	1	Rear Entry	Positive	6.2	0.3	6.5	mg/cm2	4/8/2022	14:17:55
165	To Kitchen 1 Door Stop	Wood	A	Deteriorated	White	Impact	1	Rear Entry	Positive	7.5	0.3	7.8	mg/cm2	4/8/2022	14:18:02
166	To Kitchen 1 Door Jamb	Wood	A	Deteriorated	White	Friction	1	Rear Entry	Positive	1.4	0.2	1.6	mg/cm2	4/8/2022	14:18:10
178	Window Middle Stop	Wood	7	Deteriorated	White	Friction	1	Kitchen 2	Positive	0.9	0.2	1.1	mg/cm2	4/8/2022	14:30:00
179	Window Jamb	Wood	7	Deteriorated	White	Friction	1	Kitchen 2	Positive	0.8	0.2	1	mg/cm2	4/8/2022	14:30:14
184	Cabinet Inner Frame	Wood	A	Deteriorated	Pink	Cracking	1	Kitchen 2	Positive	2.5	0.3	2.8	mg/cm2	4/8/2022	14:33:49
208	Entry Door Exterior	Wood	B	Deteriorated	White	Friction/Impact	1	Kitchen 1	Positive	0.8	0.2	1	mg/cm2	4/8/2022	14:49:13
258	Entry Door Stop	Wood	D	Deteriorated	White	Impact	1	Dining Room	Positive	44	1	45	mg/cm2	4/8/2022	15:15:07
261	Entry Door Sill	Wood	D	Deteriorated	Blue	Friction	1	Dining Room	Positive	7.1	0.3	7.4	mg/cm2	4/8/2022	15:15:36
305	Ceiling	Plaster	All	Deteriorated	White	Cracking	1	Front Entry	Positive	1.7	0.3	2	mg/cm2	4/8/2022	15:34:20
311	Entry Door Stop	Wood	A	Deteriorated	White	Impact	1	Front Entry	Positive	47	1	48	mg/cm2	4/8/2022	15:39:55

## 1514 Summit Street - Positive XRF Results

Reading	Component	Substrate	Side/#	Condition	Color	Hazard	Floor	Room	Result	Concentration	3 SD	Total Pb	Units	Date	Time
314	Entry Door Sill	Wood	A	Deteriorated	Blue	Friction	1	Front Entry	Positive	9.7	0.3	10	mg/cm2	4/8/2022	15:40:28
401	Ceiling	Plaster	All	Deteriorated	Beige	Cracking	2	Main Stairway	Positive	1	0.2	1.2	mg/cm2	4/8/2022	16:24:12
419	Ceiling	Plaster	All	Deteriorated	Beige	Cracking	2	Hallway	Positive	1.2	0.2	1.4	mg/cm2	4/8/2022	16:35:03
442	Mid Wall	Wood	B	Deteriorated	Beige	Cracking	2	Attic Stairway	Positive	3.7	0.3	4	mg/cm2	4/8/2022	16:45:28
443	Stair Tread	Wood	All	Deteriorated	Pink	Friction	2	Attic Stairway	Positive	12.4	0.5	12.9	mg/cm2	4/8/2022	16:45:38
444	Stair Riser	Wood	All	Deteriorated	Pink	Impact	2	Attic Stairway	Positive	14.3	0.5	14.8	mg/cm2	4/8/2022	16:45:46
445	Stair Stringer	Wood	All	Deteriorated	Pink	Cracking	2	Attic Stairway	Positive	3.9	0.3	4.2	mg/cm2	4/8/2022	16:45:54
447	Mid Wall Railing	Wood	-	Deteriorated	Beige	Friction	2	Attic Stairway	Positive	4.6	0.3	4.9	mg/cm2	4/8/2022	16:46:14
448	Mid Wall Newel Post	Wood	-	Deteriorated	Beige	Cracking	2	Attic Stairway	Positive	5.1	0.3	5.4	mg/cm2	4/8/2022	16:46:21
469	Window Sill	Wood	25	Deteriorated	White	Chewable	2	Bedroom 2	Positive	13.8	0.5	14.3	mg/cm2	4/8/2022	17:10:12
471	Entry Door Jamb	Wood	B	Deteriorated	White	Friction	2	Bedroom 2	Positive	10.2	0.3	10.5	mg/cm2	4/8/2022	17:12:04
474	Entry Door	Wood	B	Deteriorated	White	Friction/Impact	2	Bedroom 2	Positive	11.3	0.3	11.6	mg/cm2	4/8/2022	17:12:34
476	Closet Door Jamb	Wood	B	Deteriorated	White	Friction	2	Bedroom 2	Positive	12.7	0.3	13	mg/cm2	4/8/2022	17:12:54
477	Closet Door Stop	Wood	B	Deteriorated	White	Impact	2	Bedroom 2	Positive	8.5	0.3	8.8	mg/cm2	4/8/2022	17:13:02
481	Window Sill	Wood	12	Deteriorated	White	Cracking	2	Bedroom 2 Closet	Positive	8.3	0.3	8.6	mg/cm2	4/8/2022	17:16:36
488	Shelf	Wood	All	Deteriorated	White	Friction	2	Bedroom 2 Closet	Positive	20.9	0.5	21.4	mg/cm2	4/8/2022	17:17:54
502	Window Sill	Wood	13/14	Deteriorated	White	Chewable	2	Bedroom 3	Positive	7.3	0.3	7.6	mg/cm2	4/8/2022	17:26:31
504	Entry Door Jamb	Wood	C	Deteriorated	White	Friction	2	Bedroom 3	Positive	23.6	0.5	24.1	mg/cm2	4/8/2022	17:28:22
505	Entry Door Stop	Wood	C	Deteriorated	White	Impact	2	Bedroom 3	Positive	3.7	0.5	4.2	mg/cm2	4/8/2022	17:28:38
507	Entry Door	Wood	C	Deteriorated	White	Friction/Impact	2	Bedroom 3	Positive	14	0.3	14.3	mg/cm2	4/8/2022	17:29:04
509	Closet Door Jamb	Wood	D	Deteriorated	Beige	Friction	2	Bedroom 3	Positive	24.1	0.5	24.6	mg/cm2	4/8/2022	17:29:25
510	Closet Door Stop	Wood	D	Deteriorated	Beige	Impact	2	Bedroom 3	Positive	17.4	0.5	17.9	mg/cm2	4/8/2022	17:29:32
511	Closet Door	Wood	D	Deteriorated	White	Friction/Impact	2	Bedroom 3	Positive	28	0.5	28.5	mg/cm2	4/8/2022	17:29:43
512	Under Stair Riser	Wood	A	Deteriorated	Green	Cracking	2	Bedroom 3 Closet	Positive	22.1	0.3	22.4	mg/cm2	4/8/2022	17:36:08
513	Wall	Plaster	B	Deteriorated	Green	Cracking	2	Bedroom 3 Closet	Positive	2.6	0.3	2.9	mg/cm2	4/8/2022	17:36:22
514	Wall	Plaster	C	Deteriorated	Green	Cracking	2	Bedroom 3 Closet	Positive	4	0.3	4.3	mg/cm2	4/8/2022	17:36:38
515	Wall	Wood	D	Deteriorated	Green	Cracking	2	Bedroom 3 Closet	Positive	11.2	0.3	11.5	mg/cm2	4/8/2022	17:36:48
516	Ceiling	Wood	All	Deteriorated	Green	Cracking	2	Bedroom 3 Closet	Positive	14.7	0.3	15	mg/cm2	4/8/2022	17:36:56
521	Baseboard	Wood	All	Deteriorated	Green	Cracking	2	Bedroom 3 Closet	Positive	10.2	0.3	10.5	mg/cm2	4/8/2022	17:38:18
523	Door Casing/Header	Wood	B	Deteriorated	Beige	Cracking	2	Bedroom 3 Closet	Positive	18.7	0.5	19.2	mg/cm2	4/8/2022	17:38:38
524	Door	Wood	B	Deteriorated	Beige	Friction/Impact	2	Bedroom 3 Closet	Positive	23.6	0.5	24.1	mg/cm2	4/8/2022	17:38:54
537	Entry Door Jamb	Wood	D	Deteriorated	White	Friction	2	Bedroom 4	Positive	27.2	0.5	27.7	mg/cm2	4/8/2022	17:45:58
538	Entry Door Stop	Wood	D	Deteriorated	White	Impact	2	Bedroom 4	Positive	1.9	0.5	2.4	mg/cm2	4/8/2022	17:46:10
540	Entry Door	Wood	D	Deteriorated	White	Friction/Impact	2	Bedroom 4	Positive	12.6	0.3	12.9	mg/cm2	4/8/2022	17:46:29
541	Closet Door Casing/Header	Wood	A	Deteriorated	White	Cracking	2	Bedroom 4	Positive	20.6	0.5	21.1	mg/cm2	4/8/2022	17:46:40
542	Closet Door Jamb	Wood	A	Deteriorated	White	Friction	2	Bedroom 4	Positive	11	0.3	11.3	mg/cm2	4/8/2022	17:46:48
543	Closet Door Stop	Wood	A	Deteriorated	White	Impact	2	Bedroom 4	Positive	14.4	0.5	14.9	mg/cm2	4/8/2022	17:46:55
565	Entry Door Jamb	Wood	A	Deteriorated	White	Friction	2	Bathroom 2	Positive	5.4	0.3	5.7	mg/cm2	4/8/2022	17:57:19
566	Entry Door Stop	Wood	A	Deteriorated	White	Impact	2	Bathroom 2	Positive	2.3	0.5	2.8	mg/cm2	4/8/2022	17:57:29
569	Closet Door Casing/Header	Wood	D	Deteriorated	Beige	Cracking	2	Bathroom 2	Positive	4.9	0.3	5.2	mg/cm2	4/8/2022	17:57:59
570	Closet Door	Wood	D	Deteriorated	Beige	Friction/Impact	2	Bathroom 2	Positive	3.6	0.3	3.9	mg/cm2	4/8/2022	17:58:06
577	Shelf Underside	Wood	All	Deteriorated	White	Cracking	2	Bathroom 2 Closet	Positive	0.8	0.2	1	mg/cm2	4/8/2022	18:01:03
578	Door	Wood	B	Deteriorated	White	Friction/Impact	2	Bathroom 2 Closet	Positive	3.5	0.3	3.8	mg/cm2	4/8/2022	18:01:37
596	Window Sill	Wood	23	Deteriorated	White	Chewable	2	Bedroom 5	Positive	32	1	33	mg/cm2	4/8/2022	18:09:10
598	Entry Door Jamb	Wood	B	Deteriorated	White	Friction	2	Bedroom 5	Positive	23.9	0.5	24.4	mg/cm2	4/8/2022	18:12:56
599	Entry Door Stop	Wood	B	Deteriorated	White	Impact	2	Bedroom 5	Positive	14.2	0.5	14.7	mg/cm2	4/8/2022	18:13:04
601	Entry Door	Wood	B	Deteriorated	White	Friction/Impact	2	Bedroom 5	Positive	15.6	0.3	15.9	mg/cm2	4/8/2022	18:13:21
612	Baseboard	Wood	All	Deteriorated	White	Cracking	2	Bedroom 5 Closet	Positive	27.2	0.5	27.7	mg/cm2	4/8/2022	18:15:45
613	Shoe Molding	Wood	All	Deteriorated	White	Impact	2	Bedroom 5 Closet	Positive	1.3	0.2	1.5	mg/cm2	4/8/2022	18:16:01
622	Eave/Soffit	Wood	All	Deteriorated	White	Cracking	Exterior	Exterior	Positive	52	1	53	mg/cm2	4/8/2022	18:41:35
623	Fascia	Wood	All	Deteriorated	White	Cracking	Exterior	Exterior	Positive	51	1	52	mg/cm2	4/8/2022	18:41:44
624	Soffit Supports	Wood	All	Deteriorated	White	Cracking	Exterior	Exterior	Positive	50	1	51	mg/cm2	4/8/2022	18:41:53
629	Window Sill	Wood	12	Deteriorated	Green	Cracking	Exterior	Exterior	Positive	26.7	0.5	27.2	mg/cm2	4/8/2022	18:44:52

## 1514 Summit Street - Positive XRF Results

Reading	Component	Substrate	Side/#	Condition	Color	Hazard	Floor	Room	Result	Concentration	3 SD	Total Pb	Units	Date	Time
630	Window Casing/Header	Wood	25	Deteriorated	Green	Cracking	Exterior	Exterior	Positive	16.4	0.5	16.9	mg/cm2	4/8/2022	18:45:59
633	Window Casing/Header	Wood	9/22/24	Deteriorated	Green	Cracking	Exterior	Exterior	Positive	50	1	51	mg/cm2	4/8/2022	18:47:56
636	Window Sill	Wood	23	Deteriorated	Green	Cracking	Exterior	Exterior	Positive	1.1	0.2	1.3	mg/cm2	4/8/2022	18:48:26
638	Window Sill	Wood	1/2/10	Deteriorated	Green	Chewable	Exterior	Exterior	Positive	16.5	0.5	17	mg/cm2	4/8/2022	18:51:26
640	Entry Door Sill	Wood	A	Deteriorated	Green	Friction	Exterior	Exterior	Positive	3.2	0.3	3.5	mg/cm2	4/8/2022	18:52:26
642	Patio 1 Upper Beam	Wood	All	Deteriorated	White	Cracking	Exterior	Exterior	Positive	48	1	49	mg/cm2	4/8/2022	18:54:50
643	Patio 1 Crown Molding	Wood	All	Deteriorated	White	Cracking	Exterior	Exterior	Positive	44	1	45	mg/cm2	4/8/2022	18:55:01
644	Patio 1 Upper Trim	Wood	All	Deteriorated	White	Cracking	Exterior	Exterior	Positive	45	1	46	mg/cm2	4/8/2022	18:55:13
645	Patio 1 Soffit	Wood	All	Deteriorated	White	Cracking	Exterior	Exterior	Positive	53	1	54	mg/cm2	4/8/2022	18:55:49
648	Patio 1 Column	Wood	All	Deteriorated	White	Cracking	Exterior	Exterior	Positive	58	1	59	mg/cm2	4/8/2022	18:56:54
649	Patio 1 Lower Trim	Wood	All	Deteriorated	Green	Cracking	Exterior	Exterior	Positive	49	1	50	mg/cm2	4/8/2022	18:57:48
664	Rear Entry Door	Wood	D	Deteriorated	Green	Friction/Impact	Exterior	Exterior	Positive	44	1	45	mg/cm2	4/8/2022	19:09:36
666	Window Casing/Header	Wood	7/20/21	Deteriorated	Green	Cracking	Exterior	Exterior	Positive	46	1	47	mg/cm2	4/8/2022	19:10:51
667	Window Sill	Wood	7/20/21	Deteriorated	Green	Cracking	Exterior	Exterior	Positive	42	1	43	mg/cm2	4/8/2022	19:11:00
668	Window Casing/Header	Wood	6/8	Deteriorated	Green	Cracking	Exterior	Exterior	Positive	44	1	45	mg/cm2	4/8/2022	19:11:55
669	Window Sash	Wood	6	Deteriorated	Green	Cracking	Exterior	Exterior	Positive	16.1	0.5	16.6	mg/cm2	4/8/2022	19:12:03
670	Window Sill	Wood	6/8	Deteriorated	Green	Cracking	Exterior	Exterior	Positive	40	1	41	mg/cm2	4/8/2022	19:12:16
671	Window Exterior Stop	Wood	6/8	Deteriorated	Green	Cracking	Exterior	Exterior	Positive	27.4	0.5	27.9	mg/cm2	4/8/2022	19:12:26
672	Window Casing/Header	Wood	3/4/15-19	Deteriorated	Green	Cracking	Exterior	Exterior	Positive	50	1	51	mg/cm2	4/8/2022	19:14:02
673	Window Sill	Wood	3/4/15-19	Deteriorated	Green	Cracking	Exterior	Exterior	Positive	47	1	48	mg/cm2	4/8/2022	19:14:11
675	Window Casing/Header	Wood	5	Deteriorated	Green	Cracking	Exterior	Exterior	Positive	48	1	49	mg/cm2	4/8/2022	19:15:41
677	Patio 2 Crown Molding	Wood	All	Deteriorated	White	Cracking	Exterior	Exterior	Positive	47	1	48	mg/cm2	4/8/2022	19:19:43
678	Patio 2 Upper Beam	Wood	All	Deteriorated	White	Cracking	Exterior	Exterior	Positive	47	1	48	mg/cm2	4/8/2022	19:19:50
679	Patio 2 Upper Trim	Wood	All	Deteriorated	White	Cracking	Exterior	Exterior	Positive	44	1	45	mg/cm2	4/8/2022	19:20:02
680	Patio 2 Soffit	Wood	All	Deteriorated	White	Cracking	Exterior	Exterior	Positive	50	1	51	mg/cm2	4/8/2022	19:20:09
687	Upper Wall	Wood	A	Deteriorated	White	Cracking	Exterior	Exterior Garage	Positive	32	1	33	mg/cm2	4/8/2022	19:23:32
688	Upper Wall	Wood	B	Deteriorated	White	Cracking	Exterior	Exterior Garage	Positive	40	1	41	mg/cm2	4/8/2022	19:23:41
689	Upper Trim	Wood	All	Deteriorated	White	Cracking	Exterior	Exterior Garage	Positive	38	1	39	mg/cm2	4/8/2022	19:24:08
690	Eave/Soffit	Wood	All	Deteriorated	White	Cracking	Exterior	Exterior Garage	Positive	41	1	42	mg/cm2	4/8/2022	19:24:15
691	Fascia	Wood	All	Deteriorated	White	Cracking	Exterior	Exterior Garage	Positive	39	1	40	mg/cm2	4/8/2022	19:24:31
692	Corner Trim	Wood	All	Deteriorated	White	Cracking	Exterior	Exterior Garage	Positive	41	1	42	mg/cm2	4/8/2022	19:24:44
693	Entry Door Casing/Header	Wood	B	Deteriorated	White	Cracking	Exterior	Exterior Garage	Positive	48	1	49	mg/cm2	4/8/2022	19:25:30
694	Entry Door Jamb	Wood	B	Deteriorated	White	Friction	Exterior	Exterior Garage	Positive	50	1	51	mg/cm2	4/8/2022	19:25:39
695	Entry Door Stop	Wood	B	Deteriorated	White	Impact	Exterior	Exterior Garage	Positive	47	1	48	mg/cm2	4/8/2022	19:25:46
696	Entry Door	Wood	B	Deteriorated	Brown	Friction/Impact	Exterior	Exterior Garage	Positive	31	1	32	mg/cm2	4/8/2022	19:25:53
697	Window Casing/Header	Wood	34	Deteriorated	White	Cracking	Exterior	Exterior Garage	Positive	45	1	46	mg/cm2	4/8/2022	19:26:44
698	Window Jamb	Wood	34	Deteriorated	White	Friction	Exterior	Exterior Garage	Positive	48	1	49	mg/cm2	4/8/2022	19:26:52
699	Window Stop	Wood	34	Deteriorated	White	Impact	Exterior	Exterior Garage	Positive	42	1	43	mg/cm2	4/8/2022	19:26:59
700	Window Sill	Wood	34	Deteriorated	White	Cracking	Exterior	Exterior Garage	Positive	30	1	31	mg/cm2	4/8/2022	19:27:06
701	Window Casing/Header	Wood	34	Deteriorated	White	Cracking	Exterior	Exterior Garage	Positive	38	1	39	mg/cm2	4/8/2022	19:27:34
705	Upper Wall	Wood	D	Deteriorated	White	Cracking	Exterior	Exterior Garage	Positive	38	1	39	mg/cm2	4/8/2022	19:37:49
706	Gable Wall	Wood	C	Deteriorated	White	Cracking	Exterior	Exterior Garage	Positive	42	1	43	mg/cm2	4/8/2022	19:37:58
708	Mid Wall Trim	Wood	C	Deteriorated	White	Cracking	Exterior	Exterior Garage	Positive	3.6	0.3	3.9	mg/cm2	4/8/2022	19:39:08
709	Overhead Door Casing/Header	Wood	C	Deteriorated	White	Cracking	Exterior	Exterior Garage	Positive	28.7	0.5	29.2	mg/cm2	4/8/2022	19:39:53
711	Overhead Door Stop	Wood	C	Deteriorated	White	Impact	Exterior	Exterior Garage	Positive	27.6	0.5	28.1	mg/cm2	4/8/2022	19:40:09
713	Overhead Door Jamb	Wood	C	Deteriorated	White	Friction	Exterior	Exterior Garage	Positive	1	0.2	1.2	mg/cm2	4/8/2022	19:40:33