SPECIFICATIONS PROPOSAL & BID DOCUMENT

IALHB0664-18 – 024 Property: 422 S Cecelia Street

Sioux City, Iowa

Lead Based Paint Remediation must be completed in <u>10 days</u> from receiving the Notice to Proceed

All projects with costs of \$20,000 or more are subject to HUD's pre-approval prior to issuance of a Notice to Proceed.

BIDS ARE DUE at the following location on XXXXXXXX no later than 4:00 p.m.

City of Sioux City: Neighborhood Services Division

Attn: Ron Engle

405 6th Street, Room 305

P.O. Box 447

Sioux City, IA 51102

NON-COLLUSION AFFIDAVIT OF PRIME BIDDER

STATE	,
COUNT) SS: Y OF)
	, being first duly sworn, deposes and says
that:	
(1)	He is of (Owner, partner, office, representative, agent, other, explain), the Bidder that has submitted the
(2)	attached Bid; He is fully informed respecting the preparation and contents of the attached Bid and of all pertinent circumstances respecting such bid;
(3) (4)	Such Bid is genuine and is not a collusive or sham Bid; Neither the said Bidder nor any of its officers, partners, owner, agents, representatives, employees or parties in including this affiant, nor any employee or official of the City of Sioux City has in any way colluded, conspired, connived or agreed, directly or indirectly, with any other Bidder, firm or person to submit a sham bid in connection with the Contract for which the attached Bids have been submitted or to refrain from bidding in connection with such Contract, or has in any manner, directly or indirectly, sought by agreement or collusion or communication or conference with any other Bidder, firm or person to fix the price or prices in the attached Bid or of any other Bidder, or to fix overhead, profit or cost element of the Bid price or the Bid price of any other Bidder, or to secure through any collusion, conspiracy, connivance or unlawful agreement, any advantage against the City of Sioux City or the owner of the property interested in the proposed contract; The prices quoted in the attached Bid are fair and proper and are not tainted by any collusion, conspiracy, connivance or unlawful agreement on the part of Bidder or any of its agents, representatives, owners, employers or parties in interest including this affiant, or by any employee or official of the City of Sioux City.
	SIGNED
	TITLE

SIOUX CITY LEAD HAZARD CONTROL PROGRAM BID AND PROPOSAL

PROJECT SPECIFICATIONS FOR PROPERTY LOCATED AT:

422 S Cecelia Street Sioux City, Iowa 51106

The proposal of	(hereinafter called "Bidder"), organized and
existing under the laws of the State of	doing business as
* . (*Insert "a corporation", "a pai	rtnership", or "an individual" as applicable.)
	1, , , , , , , , , , , , , , , , , , ,
To the City of Sioux City, Iowa (hereinafter called	'COMMUNITY").
In compliance with your Advertisement for Bids WORK for the project located at the above referer joint BID, each party thereto certifies as to his own at independently, without consultation, communicated the bid	nced property certifies, and, in the case of a organization, that this BID has been arrived ation, or agreement as to any matter related
BIDDER hereby agrees to commence work undespecified in the Notice to Proceed.	er this proposal on or before a date to be
BIDDER acknowledges receipt and Instructions to Bidder:	complete understanding of the
Printed or typed name of BIDDER / CONTRACTOR	
Signature of BIDDER / CONTRACTOR	

LINE ITEM PRICING

(CONTRACTOR TO VERIFY QUANTITIES DURING WALKTHROUGH)

NOTE(S): 1) All finish work to be completed per the Bidding Instructions.

- 2) You are responsible for repairing any damage to components remaining in place (i.e. header and casings as part of window replacement).
- 3) Per lowa Admin Code 641-70.2(135) ""Paint Stabilization" means repairing any physical defect in the substrate…"

LINE		LEAD
# INTERIOR DIVISION	LIRA	PRICE
1 Basement, Room 1, Windows (#14,15) – Abatement - Remove		
and replace Window Components. Remove any unnecessary		
storm windows and ensure all painted surfaces exposed by the		
activity are covered in a suitable weather resistant material that		
matches the surrounding. Caulk seams to create dust tight seal		
2 Basement, Room 1, Window (#17) – Abatement - Remove and		
replace Header, Casing and Sill. If any portion of the previously		
stated components cannot be removed or is exposed please		
cover that portion in a wear-resistant material and caulk the		
seams to create a dust-tight seal. Paint the components to		
match the surrounding.		
3 Basement, Room 1, Entry Door Frame (Side C) – Strip paint		
from components and photograph for documentation, repaint		
with two coats of high quality appropriate paint.		
4 Floor 1, Kitchen, Wall & Ceiling (All) – Interim – Paint		
Stabilization followed by two coats of high quality appropriate		
paint. Repaint to match existing.	12	
5 Floor 1, Kitchen, Windows (#8,9) – Abatement - Remove and		
replace Window Components. Remove any unnecessary storm		
windows and ensure all painted surfaces exposed by the activity		
are covered in a suitable weather resistant material that matches	S	
the surrounding. Caulk seams to create dust tight seal.		
6 Floor 1, Kitchen, Entry Door, Stop, Threshold, Sill (Side D) –		
Abatement – Strip paint from all and photograph for		
documentation, repaint all with two coats of high quality		
appropriate paint. 7 Floor 1. Dining Room, Walls B.C.D & Ceiling – Interim – Paint		
7 Floor 1, Dining Room, Walls B,C,D & Ceiling – Interim – Paint Stabilization followed by two coats of high quality appropriate		
paint. Repaint to match existing.		
8 Floor 1, Dining Room, Windows (#s 10-12) – Abatement -		
Remove and replace Window Components. Remove any		
unnecessary storm windows and ensure all painted surfaces		
exposed by the activity are covered in a suitable weather		
resistant material that matches the surrounding. Caulk seams to	,	
create dust tight seal.		
9 Floor 1, Hallway, Wall B,C & Ceiling – Interim – Paint		
Stabilization followed by two coats of high quality appropriate		
paint. Repaint to match existing.		

10			
	Floor 1, Bedroom 2, Windows (#s 6,7) – Abatement - Remove		
	and replace Window Components. Remove any unnecessary		
	storm windows and ensure all painted surfaces exposed by the		
	activity are covered in a suitable weather resistant material that		
	matches the surrounding. Caulk seams to create dust tight seal.		
11	Floor 1, Bedroom 1, Window (#5) – Abatement - Remove and		
	replace Window Components. Remove any unnecessary storm		
	windows and ensure all painted surfaces exposed by the activity		
	are covered in a suitable weather resistant material that matches		
	the surrounding. Caulk seams to create dust tight seal.		
12	Floor 1, Living Room, Wall B,C,D & Ceiling - Interim - Paint		
	Stabilization followed by two coats of high quality appropriate		
	paint. Repaint to match existing.		
12			
13	Floor 1, Living Room, Windows (#s 1-4,13) – Abatement -		
	Remove and replace Window Components. Remove any		
	unnecessary storm windows and ensure all painted surfaces		
	exposed by the activity are covered in a suitable weather		
	resistant material that matches the surrounding. Caulk seams to		
	create dust tight seal.		
14	Floor 1, Living Room, Entry Door Stop and Sill (Side A) –		
	Abatement - Strip paint from all and photograph for		
	documentation, repaint all with two coats of high quality		
	appropriate paint.		
			DDICE
NOTE	EXTERIOR DIVISION		PRICE
	If due to colder weather, some or all exterior work may be postpon		
	ns. Please make sure that your prices incorporate this, as NO char	nge or	aers wiii
	ed for additional travel expenses.	1	
***	If any painted areas are exposed during the completion of		
	hand de a de la colonia de		
1	activities the price to treat those areas to the same level as the		
	line item should be included.		X
15	line item should be included.		Х
15	line item should be included. Exterior, Upper Trim/Eave/Soffit/Fascia/Truss Ends Interim -		Х
15	line item should be included. Exterior, Upper Trim/Eave/Soffit/Fascia/Truss Ends Interim - Paint Stabilization followed by two coats of high quality		Х
	line item should be included. Exterior, Upper Trim/Eave/Soffit/Fascia/Truss Ends Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing.		X
15	line item should be included. Exterior, Upper Trim/Eave/Soffit/Fascia/Truss Ends Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing. Exterior, Window Frame and Sash (#16) – Interim - Paint		X
	line item should be included. Exterior, Upper Trim/Eave/Soffit/Fascia/Truss Ends Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing. Exterior, Window Frame and Sash (#16) – Interim - Paint Stabilization followed by two coats of high quality appropriate		X
16	line item should be included. Exterior, Upper Trim/Eave/Soffit/Fascia/Truss Ends Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing. Exterior, Window Frame and Sash (#16) – Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing		X
	line item should be included. Exterior, Upper Trim/Eave/Soffit/Fascia/Truss Ends Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing. Exterior, Window Frame and Sash (#16) – Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing Exterior, Exposed Underside of Siding (Side B) – Abatement -		X
16	line item should be included. Exterior, Upper Trim/Eave/Soffit/Fascia/Truss Ends Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing. Exterior, Window Frame and Sash (#16) – Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing		X
16	line item should be included. Exterior, Upper Trim/Eave/Soffit/Fascia/Truss Ends Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing. Exterior, Window Frame and Sash (#16) – Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing Exterior, Exposed Underside of Siding (Side B) – Abatement -		X
16	line item should be included. Exterior, Upper Trim/Eave/Soffit/Fascia/Truss Ends Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing. Exterior, Window Frame and Sash (#16) – Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing Exterior, Exposed Underside of Siding (Side B) – Abatement - Paint Stabilization followed by installation of wear resistant material, caulk seams to create a dust-tight seal.		X
16	line item should be included. Exterior, Upper Trim/Eave/Soffit/Fascia/Truss Ends Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing. Exterior, Window Frame and Sash (#16) – Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing Exterior, Exposed Underside of Siding (Side B) – Abatement - Paint Stabilization followed by installation of wear resistant material, caulk seams to create a dust-tight seal. Exterior, Entry Door, Casing and Header (Side C) – Interim -		X
16	line item should be included. Exterior, Upper Trim/Eave/Soffit/Fascia/Truss Ends Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing. Exterior, Window Frame and Sash (#16) – Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing Exterior, Exposed Underside of Siding (Side B) – Abatement - Paint Stabilization followed by installation of wear resistant material, caulk seams to create a dust-tight seal. Exterior, Entry Door, Casing and Header (Side C) – Interim - Paint Stabilization followed by two coats of high quality		X
16 17 18	line item should be included. Exterior, Upper Trim/Eave/Soffit/Fascia/Truss Ends Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing. Exterior, Window Frame and Sash (#16) – Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing Exterior, Exposed Underside of Siding (Side B) – Abatement - Paint Stabilization followed by installation of wear resistant material, caulk seams to create a dust-tight seal. Exterior, Entry Door, Casing and Header (Side C) – Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing		X
16	Exterior, Upper Trim/Eave/Soffit/Fascia/Truss Ends Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing. Exterior, Window Frame and Sash (#16) – Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing Exterior, Exposed Underside of Siding (Side B) – Abatement - Paint Stabilization followed by installation of wear resistant material, caulk seams to create a dust-tight seal. Exterior, Entry Door, Casing and Header (Side C) – Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing Exterior, Entry Door, Casing and Header (Side A) – Interim -		X
16 17 18	Exterior, Upper Trim/Eave/Soffit/Fascia/Truss Ends Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing. Exterior, Window Frame and Sash (#16) – Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing Exterior, Exposed Underside of Siding (Side B) – Abatement - Paint Stabilization followed by installation of wear resistant material, caulk seams to create a dust-tight seal. Exterior, Entry Door, Casing and Header (Side C) – Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing Exterior, Entry Door, Casing and Header (Side A) – Interim - Paint Stabilization followed by two coats of high quality		X
16 17 18 19	Exterior, Upper Trim/Eave/Soffit/Fascia/Truss Ends Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing. Exterior, Window Frame and Sash (#16) – Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing Exterior, Exposed Underside of Siding (Side B) – Abatement - Paint Stabilization followed by installation of wear resistant material, caulk seams to create a dust-tight seal. Exterior, Entry Door, Casing and Header (Side C) – Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing Exterior, Entry Door, Casing and Header (Side A) – Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing		X
16 17 18	Exterior, Upper Trim/Eave/Soffit/Fascia/Truss Ends Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing. Exterior, Window Frame and Sash (#16) – Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing Exterior, Exposed Underside of Siding (Side B) – Abatement - Paint Stabilization followed by installation of wear resistant material, caulk seams to create a dust-tight seal. Exterior, Entry Door, Casing and Header (Side C) – Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing Exterior, Entry Door, Casing and Header (Side A) – Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing Exterior, Window (#20) – Abatement - Remove and replace		X
16 17 18 19	Exterior, Upper Trim/Eave/Soffit/Fascia/Truss Ends Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing. Exterior, Window Frame and Sash (#16) – Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing Exterior, Exposed Underside of Siding (Side B) – Abatement - Paint Stabilization followed by installation of wear resistant material, caulk seams to create a dust-tight seal. Exterior, Entry Door, Casing and Header (Side C) – Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing Exterior, Entry Door, Casing and Header (Side A) – Interim - Paint Stabilization followed by two coats of high quality appropriate paint. Repaint to match existing		X

	windows and ensure all painted surfaces exposed by the activity	
	are covered in a suitable weather resistant material that matches	
	the surrounding. Caulk seams to create dust tight seal.	
21	Exterior, Porch, Ceiling/Upper Beam/Crown	
	Molding/Eave/Soffit/Fascia (All) – Interim - Paint Stabilization	
	followed by two coats of high quality appropriate paint. Repaint	
	to match existing	
	CLEAN UP AND CONTAINMENT DIVISION	PRICE
	This section includes containment and clean-up and waste removal. It may or	
	may not include wrapping of large pieces of furniture and/or appliances.	
	Contractor must clean dwelling sufficiently to pass clearance testing. If	
	containment is utilized, contractor is responsible for establishing containment. If dwelling does not pass clearance on the first attempt, the contractor is	
	responsible for costs associated with subsequent attempts. This line item	
	shall not exceed \$1,500.	\$
	POST REMEDIATION TESTING AND CLEARANCE	PRICE
	Pre-negotiated price for the entirety of the 2018 LHCG. This amount is	
	payable to Impact 7G., Inc. If there are any failed visual inspections they will	
	be billed at a rate of \$300.00 per occurrence, if there are additional	
	inspections that require dust or soil sampling they will be billed at a rate of \$600.00 per occurrence. Any amounts incurred over the initial \$900.00 are	
	the responsibility of the contractor.	\$ 900

BI	D SUMMARY (422 S Cecelia Street)		Base Bid Price		
	INTERIOR DIVISION TOTAL	L	<u> </u>		
			<u> </u>		
	EXTERIOR DIVISION TOTAL		<u> </u>		
	CLEAN-UP AND WASTE DIVISION TOTAL		\$		
	TESTING AND CLEARANCE	= 3	\$ 900		
	TOTAL AMOUNT FOR LEAD BASE BII) (2		
	TOTAL AMOUNT FOR LEAD BASE BID \$				
	ALTERNATE BID ITEMS				
			Alternate		
			Pricing		
NOTE: Provide the TOTAL cost for the alternate bid items. If an alternate bid item is selected, the provided cost will replace the costs designated in the "Remove Lines."					
Alt	, ,				
	stabilize followed by the installation of a weather resistant				
	material. Caulk seams to create a dust tight seal. This will				
	replace Line Item #15 (Please list full price to complete this				
	line item from current condition)	9	\$		

Alt	Exterior, Porch, Ceiling/Upper Beam/Crown	
	Molding/Eave/Soffit/Fascia (All) - Abatement - Paint	
	Stabilization followed by the installation of a weather resistant	
	material, caulk seams to create a dust tight seal. Tis will	
	eliminate the need for Line Item #21. (Please list full price to	
	complete this line item from current condition)	

Section to be filled in by City:

ACCEPTED HEALTHY HOMES ALTERNATES	\$	
ACCEPTED LBP ALTERNATES	\$	
ADJUSTED BASE BID TOTAL	\$	





