SPECIFICATIONS PROPOSAL & BID DOCUMENT

IALHB0664-18 – <mark>0</mark>89 Property: 513 12th Street Unit 5

Sioux City, Iowa

Lead Based Paint Remediation must be completed in <u>10 days</u> from receiving the Notice to Proceed

All projects with costs of \$20,000 or more are subject to HUD's pre-approval prior to issuance of a Notice to Proceed.

BIDS ARE DUE at the following location on 09/03/2021 no later than 4:00 p.m.

City of Sioux City: Neighborhood Services Division

Attn: Matt Meylor

405 6th Street, Room 305

P.O. Box 447

Sioux City, IA 51102

NON-COLLUSION AFFIDAVIT OF PRIME BIDDER

STATE	,
COUNT) SS: Y OF)
	, being first duly sworn, deposes and says
that:	
(1)	He is of (Owner, partner, office, representative, agent, other, explain), the Bidder that has submitted the
(2)	attached Bid; He is fully informed respecting the preparation and contents of the attached Bid and of all pertinent circumstances respecting such bid;
(3) (4)	Such Bid is genuine and is not a collusive or sham Bid; Neither the said Bidder nor any of its officers, partners, owner, agents, representatives, employees or parties in including this affiant, nor any employee or official of the City of Sioux City has in any way colluded, conspired, connived or agreed, directly or indirectly, with any other Bidder, firm or person to submit a sham bid in connection with the Contract for which the attached Bids have been submitted or to refrain from bidding in connection with such Contract, or has in any manner, directly or indirectly, sought by agreement or collusion or communication or conference with any other Bidder, firm or person to fix the price or prices in the attached Bid or of any other Bidder, or to fix overhead, profit or cost element of the Bid price or the Bid price of any other Bidder, or to secure through any collusion, conspiracy, connivance or unlawful agreement, any advantage against the City of Sioux City or the owner of the property interested in the proposed contract; The prices quoted in the attached Bid are fair and proper and are not tainted by any collusion, conspiracy, connivance or unlawful agreement on the part of Bidder or any of its agents, representatives, owners, employers or parties in interest including this affiant, or by any employee or official of the City of Sioux City.
	SIGNED
	TITLE

SIOUX CITY LEAD HAZARD CONTROL PROGRAM BID AND PROPOSAL

PROJECT SPECIFICATIONS FOR PROPERTY LOCATED AT:

513 12th Street Unit 5 Sioux City, Iowa 51105

The proposal of	(hereinafter called "Bidder"), organized and doing business as partnership", or "an individual" as applicable.)						
To the City of Sioux City, Iowa (hereinafter called	"COMMUNITY").						
In compliance with your Advertisement for Bids WORK for the project located at the above refere joint BID, each party thereto certifies as to his own at independently, without consultation, communic to this BID with any other BIDDER or with any core	nced property certifies, and, in the case of a organization, that this BID has been arrived ation, or agreement as to any matter related						
BIDDER hereby agrees to commence work und specified in the Notice to Proceed.	er this proposal on or before a date to be						
BIDDER acknowledges receipt and Instructions to Bidder:	complete understanding of the						
Printed or typed name of BIDDER / CONTRACTOR	<u> </u>						
Signature of BIDDER / CONTRACTOR							

LINE ITEM PRICING

(CONTRACTOR TO VERIFY QUANTITIES DURING WALKTHROUGH)

- NOTE(S): 1) All finish work to be completed per the Bidding Instructions.
 - 2) You are responsible for repairing any damage to components remaining in place (i.e. header and casings as part of window replacement).
 - 3) Per lowa Admin Code 641-70.2(135) ""Paint Stabilization" means repairing any physical defect in the substrate…"


LINE	ITEM		LEAD				
#	INTERIOR DIVISION	LIRA	PRICE				
1	Floor 2, Living Room Closet, Baseboard (Side All White) -						
	Interim – Paint stabilization followed by the installation of two	440					
	coats of high-quality appropriate paint to match existing.						
2	Floor 2, Living Room Closet, Shoe Molding (Side All White) -						
	Abatement – Remove and replace component followed by the						
	application of two coats of high quality paint to match	441					
	surrounding.						
3	Floor 2, Kitchen, Cabinet Door, (Side D White) - Abatement -						
	Strip paint 2 inches from all impact/friction surfaces and						
	photograph for documentation / paint stabilization on the entire						
	side of failing component followed by the application of two coats						
	of high-quality appropriate paint.						
4	Floor 2, Bathroom 1, Windows, Sill/Middle Stop/Jamb/Stop (#s						
	35) – Abatement - Remove and replace Window Components.						
	Remove any unnecessary storm windows and ensure all painted						
	surfaces exposed by the activity are covered in a suitable	470 471					
	weather resistant material that matches the surrounding. Caulk						
	seams to create dust tight seal. Sill – Abatement – Strip paint	472					
	from components and photograph for documentation. Apply two						
	coats of high quality appropriate paint to match surrounding.						
	g.						
	EXTERIOR DIVISION		PRICE				
NOTE:	ed unt	il warmer					
	ns. Please make sure that your prices incorporate this, as NO cha						
	ed for additional travel expenses.	Ü					
***	If any painted areas are exposed during the completion of						
	activities the price to treat those areas to the same level as the						
	line item should be included.		X				
	CLEAN UP AND CONTAINMENT DIVISION		PRICE				
	This section includes containment and clean-up and waste removal. It may or						
	may not include wrapping of large pieces of furniture and/or appliances.						
	Contractor must clean dwelling sufficiently to pass clearance testing. If						
	containment is utilized, contractor is responsible for establishing containment. If dwelling does not pass clearance on the first attempt, the contractor is						
	responsible for costs associated with subsequent attempts. This line item						
		\$					
	POST REMEDIATION TESTING AND CLEARANCE		PRICE				


Pre-negotiated price for the entirety of the 2018 LHCG. This amount is payable to Impact 7G., Inc. If there are any failed visual inspections they will be billed at a rate of \$300.00 per occurrence, if there are additional inspections that require dust or soil sampling they will be billed at a rate of \$600.00 per occurrence. Any amounts incurred over the initial \$900.00 are the responsibility of the contractor.	\$ 900


BI		Base Bid Price						
	INTERIOR DIVISION TOTA	L \$						
	EXTERIOR DIVISION TOTA							
	CLEAN-UP AND WASTE DIVISION TOTA							
	TESTING AND CLEARANC	E \$	900					
	TOTAL AMOUNT FOR LEAD BASE BI	D \$						
ALTERNATE BID ITEMS								
			Alternate Pricing					
	Provide the TOTAL cost for the alternate bid items. If an alternate bid it cost will replace the costs designated in the "Remove Lines."	tem is	Pricing					
		tem is	Pricing s selected, the					
provided	cost will replace the costs designated in the "Remove Lines." Install provided Smoke and Carbon Monoxide Detectors. Price		Pricing s selected, the					
provided HH Alt	cost will replace the costs designated in the "Remove Lines." Install provided Smoke and Carbon Monoxide Detectors. Price		Pricing s selected, the					
provided HH Alt HH Alt	cost will replace the costs designated in the "Remove Lines." Install provided Smoke and Carbon Monoxide Detectors. Price		Pricing s selected, the					
Provided HH Alt HH Alt HH Alt	cost will replace the costs designated in the "Remove Lines." Install provided Smoke and Carbon Monoxide Detectors. Price		Pricing s selected, the					


Section to be filled in by City:


cocher to be inica in by city:	
ACCEPTED HEALTHY HOMES ALTERNATES	\$
ACCEPTED LBP ALTERNATES	\$
ADJUSTED BASE BID TOTAL	\$











515 12th Street, APT 3 - Table 1-XRF Results

Reading #	Component	Substrate	Side/#	Condition	Color	Hazard	Floor	Room	Result	Concentration	3 SD	Total Pb	Units	Date	Time	Unit
440	Baseboard	Wood	All	Deteriorated	White	Cracking	2	Living Room Closet	Positive	8.4	0.3	8.7	mg/cm2	6/22/2021	17:03:05	513-5
441	Shoe Molding	Wood	All	Deteriorated	White	Cracking	2	Living Room Closet	Positive	4.3	0.3	4.6	mg/cm2	6/22/2021	17:03:15	513-5
454	Cabinet Door	Wood	D	Deteriorated	White	Friction/Impact	2	Kitchen	Positive	0.9	0.2	1.1	mg/cm2	6/22/2021	17:09:18	513-5
470	Window Sill	Wood	35	Deteriorated	White	Chewable	2	Bathroom 1	Positive	1.1	0.2	1.3	mg/cm2	6/22/2021	17:14:53	513-5
471	Window Middle Stop	Wood	35	Deteriorated	Beige	Friction	2	Bathroom 1	Positive	5.5	0.3	5.8	mg/cm2	6/22/2021	17:15:30	513-5
472	Window Jamb/Stop	Wood	35	Deteriorated	Beige	Friction	2	Bathroom 1	Positive	16.7	0.3	17	mg/cm2	6/22/2021	17:15:39	513-5
474	Window Exterior Stop	Wood	35	Deteriorated	Red	Friction	2	Bathroom 1	Positive	19.3	0.3	19.6	mg/cm2	6/22/2021	17:15:58	513-5