# SPECIFICATIONS PROPOSAL & BID DOCUMENT

IALHB0664-18 – 023 Property: 2917 Myrtle Street

# Sioux City, Iowa

Lead Based Paint Remediation must be completed in <u>10 days</u> from receiving the Notice to Proceed

All projects with costs of \$20,000 or more are subject to HUD's pre-approval prior to issuance of a Notice to Proceed.

BIDS ARE DUE at the following location on XXXXXXXX no later than 4:00 p.m.

City of Sioux City: Neighborhood Services Division

Attn: Ron Engle

405 6<sup>th</sup> Street, Room 305

P.O. Box 447

Sioux City, IA 51102

## NON-COLLUSION AFFIDAVIT OF PRIME BIDDER

STATE	,
COUNT	) SS: Y OF)
	, being first duly sworn, deposes and says
that:	
(1)	He is of (Owner, partner, office, representative, agent, other, explain), the Bidder that has submitted the
(2)	attached Bid; He is fully informed respecting the preparation and contents of the attached Bid and of all pertinent circumstances respecting such bid;
(3) (4)	Such Bid is genuine and is not a collusive or sham Bid; Neither the said Bidder nor any of its officers, partners, owner, agents, representatives, employees or parties in including this affiant, nor any employee or official of the City of Sioux City has in any way colluded, conspired, connived or agreed, directly or indirectly, with any other Bidder, firm or person to submit a sham bid in connection with the Contract for which the attached Bids have been submitted or to refrain from bidding in connection with such Contract, or has in any manner, directly or indirectly, sought by agreement or collusion or communication or conference with any other Bidder, firm or person to fix the price or prices in the attached Bid or of any other Bidder, or to fix overhead, profit or cost element of the Bid price or the Bid price of any other Bidder, or to secure through any collusion, conspiracy, connivance or unlawful agreement, any advantage against the City of Sioux City or the owner of the property interested in the proposed contract;  The prices quoted in the attached Bid are fair and proper and are not tainted by any collusion, conspiracy, connivance or unlawful agreement on the part of Bidder or any of its agents, representatives, owners, employers or parties in interest
	including this affiant, or by any employee or official of the City of Sioux City.
	SIGNED
	TITLE

#### SIOUX CITY LEAD HAZARD CONTROL PROGRAM BID AND PROPOSAL

### PROJECT SPECIFICATIONS FOR PROPERTY LOCATED AT:

#### 2917 Myrtle Street Sioux City, Iowa 51103

The proposal ofexisting under the laws of the State of* (*Insert "a corporation", "a pa	(hereinafter called "Bidder"), organized and doing business as
To the City of Sioux City, Iowa (hereinafter called	"COMMUNITY").
In compliance with your Advertisement for Bids WORK for the project located at the above refere joint BID, each party thereto certifies as to his own at independently, without consultation, communic to this BID with any other BIDDER or with any cor	nced property certifies, and, in the case of a organization, that this BID has been arrived ation, or agreement as to any matter related
BIDDER hereby agrees to commence work und specified in the Notice to Proceed.	er this proposal on or before a date to be
BIDDER acknowledges receipt and Instructions to Bidder:	complete understanding of the
Printed or typed name of BIDDER / CONTRACTOR	
Signature of BIDDER / CONTRACTOR	

#### **LINE ITEM PRICING**

### (CONTRACTOR TO VERIFY QUANTITIES DURING WALKTHROUGH)

NOTE(S): 1) All finish work to be completed per the Bidding Instructions.

- 2) You are responsible for repairing any damage to components remaining in place (i.e. header and casings as part of window replacement).
- 3) Per lowa Admin Code 641-70.2(135) ""Paint Stabilization" means repairing any physical defect in the substrate..."

LINE	ITEM		LEAD
#	INTERIOR DIVISION	LIRA	PRICE
1	Basement, Workout Area, Windows, Frame/Sash/Stop (#s	LIIVA	FRICE
1	11,12) – Abatement - Remove and replace Window		
	Components. Remove any unnecessary storm windows and		
	ensure all painted surfaces exposed by the activity are covered		
	in a suitable weather resistant material that matches the		
	surrounding. Caulk seams to create dust tight seal.		
2	Basement, Room 1, Support Post, White-Wood – Interim – Paint		
_	Stabilization followed by two coats of high quality appropriate		
	paint. Repaint to match existing.		
3	Basement, Room 1, Closet Door, White-Wood (Side B) – Interim		
	Remove paint from all friction and impact surfaces and		
	photograph for documentation followed by the application of two		
	coats of high quality appropriate paint. Repaint to match existing.		
4	Basement, Room 1, Windows, Frame/Sash (#s 10,13-15) -		
	Abatement - Remove and replace Window Components.		
	Remove any unnecessary storm windows and ensure all painted		
	surfaces exposed by the activity are covered in a suitable		
	weather resistant material that matches the surrounding. Caulk		
	seams to create dust tight seal.	12	
5	Basement, Basement Stairway, Joist Cap (Side D) - Interim -		
	Paint Stabilization followed by two coats of high quality		
	appropriate paint. Repaint to match existing.		
6	Basement, Basement Stairway, Stair Tread Support/Stair		
	Stringer (All) – Interim – Paint Stabilization followed by two coats		
	of high quality appropriate paint. Repaint to match existing.		
7	Basement, Basement Stairway, Stair Tread/Riser (All) - Interim		
	<ul> <li>Paint Stabilization followed by the installation of a wear</li> </ul>		
	resistant material.		
8	Floor 1, Rear Entry, Joist-Cap(Side D)/Wall Cap (Side A,C) –		
	Abatement – Remove paint from components and photograph		
	for documentation followed by the application of two coats of		
0	high quality appropriate paint.		
9	Floor 1, Rear Entry, Stair Riser (Side B) – Interim – Paint Stabilization followed by the installation of a wear resistant		
	material.		
10	Floor 1, Rear Entry, Entry Door Sill (Side C) – Abatement -		
	Remove paint from components and photograph for		
	Remove paint from components and photograph for		

	documentation followed by the application of two coats of high	
	quality appropriate paint.	
11	Floor 1, Kitchen, Ceiling (All) - – Interim – Paint Stabilization	
	followed by two coats of high quality appropriate paint. Repaint	
	to match existing.	
12	Floor 1, Kitchen, Windows, Middle Stop/Jamb/Exterior Stop (#s	
12	5,6) – Abatement - Remove and replace Window Components.	
	Remove any unnecessary storm windows and ensure all painted	
	surfaces exposed by the activity are covered in a suitable	
	weather resistant material that matches the surrounding. Caulk	
	seams to create dust tight seal.	
13	Floor 1, Kitchen, Upper Cabinet Shelf (Side B, D) – Abatement –	
13	Remove and replace shelves paint to match surrounding OR	
	remove paint from component and photograph for	
	documentation followed by the application of two coats of high-	
	quality appropriate paint to match surrounding.	
14	Floor 1, Dining Room, Windows, Middle Stop/Jamb/Exterior Stop	
14	(#s 4) – Abatement - Remove and replace Window Components.	
	Remove any unnecessary storm windows and ensure all painted	
	surfaces exposed by the activity are covered in a suitable	
	weather resistant material that matches the surrounding. Caulk	
	seams to create dust tight seal.	
15	Floor 1, Living Room, Windows, Middle Stop/Jamb/Exterior Stop	
13	(#s 2,3) – Abatement - Remove and replace Window	
	Components. Remove any unnecessary storm windows and	
	ensure all painted surfaces exposed by the activity are covered	
	in a suitable weather resistant material that matches the	
	surrounding. Caulk seams to create dust tight seal.	
16	Floor 1, Living Room, Entry Door Sill (Side A) - Abatement -	
	Remove paint from component and photograph for	
	documentation followed by the application of two coats of high	
	quality appropriate paint.	
17	Floor 1, Bedroom 1, Windows, Upper sash/Lower Sash/Inside	
	Stop/Middle Stop/Exterior Stop (#s 1,9) – Abatement - Remove	
	and replace Window Components. Remove any unnecessary	
	storm windows and ensure all painted surfaces exposed by the	
	activity are covered in a suitable weather resistant material that	
	matches the surrounding. Caulk seams to create dust tight seal.	
18	Floor 1, Bedroom 1, Window, Sill (#s 1,9) – Abatement –	
	Remove paint from component and photograph for	
	documentation followed by the application of two coats of high-	
	quality appropriate paint.	
19	Floor 1, Bedroom 1 Closet, Shoe Molding (All) – Abatement –	
	Remove and replace component treat to match surrounding.	
20	Floor 1, Hallway, Wall Cabinet Sill/Shelf (Side D) – Abatement –	
	Remove and replace components and treat to match	
	surrounding OR remove paint from components and photograph	

	for documentation followed by the application of two coats of		
	high-quality appropriate paint.		
21	Floor 1, Bedroom 2, Windows, Middle Stop/Exterior Stop (#s		
	7,8) - Abatement - Remove and replace Window Components.		
	Remove any unnecessary storm windows and ensure all painted		
	surfaces exposed by the activity are covered in a suitable		
	weather resistant material that matches the surrounding. Caulk		
	seams to create dust tight seal.		
	EXTERIOR DIVISION		PRICE
NOTE:	If due to colder weather, some or all exterior work may be postpon	ed unt	il warme
conditio	ns. Please make sure that your prices incorporate this, as NO char	nge or	ders will
be issue	ed for additional travel expenses.		
***	If any painted areas are exposed during the completion of		
	activities the price to treat those areas to the same level as the		
	line item should be included.		X
22	Exterior, Window Storm Sash (#1) - Interim - Paint Stabilization		
	followed by two coats of high quality appropriate paint. Repaint		
	to match existing.		
23	Exterior, Entry Door, Sill (Side C) – Abatement – Scrape paint		
	from component and photograph for documentation followed by		
	the application of two coats of high-quality appropriate paint to		
	match surrounding.		
	CLEAN UP AND CONTAINMENT DIVISION		PRICE
	This section includes containment and clean-up and waste removal. It may or may not include wrapping of large pieces of furniture and/or appliances.		
	Contractor must clean dwelling sufficiently to pass clearance testing. If		
	containment is utilized, contractor is responsible for establishing containment.  If dwelling does not pass clearance on the first attempt, the contractor is		
	responsible for costs associated with subsequent attempts. <b>This line item</b>		
	shall not exceed \$1,500.		\$
	POST REMEDIATION TESTING AND CLEARANCE		PRICE
	Pre-negotiated price for the entirety of the 2018 LHCG. This amount is payable to Impact 7G., Inc. If there are any failed visual inspections they will		
	be billed at a rate of \$300.00 per occurrence, if there are additional		
	inspections that require dust or soil sampling they will be billed at a rate of \$600.00 per occurrence. Any amounts incurred over the initial \$900.00 are		
	the responsibility of the contractor.		\$ 900

BID SUMMARY (1309 22 <sup>nd</sup> Street)	Base Bid Price
INTERIOR DIVISION TOTAL	\$
EXTERIOR DIVISION TOTAL	\$
CLEAN-UP AND WASTE DIVISION TOTAL	\$

TESTING AND CLEARAN	CE	\$ 900	
TOTAL AMOUNT FOR LEAD BASE I	מוא	\$	
TOTAL AMOUNT TOK ELAD BACE I	טונ	Ψ	
ALTERNATE BID ITEMS			
		Alternate Pricing	
<b>NOTE:</b> Provide the TOTAL cost for the alternate bid items. If an alternate bid item is selected, the provided cost will replace the costs designated in the "Remove Lines."			
Alt		\$	

Section to be filled in by City:

ACCEPTED HEALTHY HOMES ALTERNATES	\$
ACCEPTED LBP ALTERNATES	\$
ADJUSTED BASE BID TOTAL	\$





